Software Performance Summary

LAB-8/e and PDP-12

JANUARY 1974

The material in this document is for information purposes only and is subject to change without notice. Digital Equipment Corporation assumes no responsibility for any errors which may appear in this document.

SOFTWARE ENGINEERING AND SERVICES SOFTWARE COMMUNICATIONS Digital Equipment Corporation Maynard, MA 01754



Copyright 1974, DIGITAL EQUIPMENT CORPORATION

The following are trademarks of Digital Equipment Corporation, Maynard, Massachusetts:

DIGITAL LAB-K **DEC DATA SYSTEMS** DEC SABR COMTEX-11 PDP TYPESET-8 QUICKPOINT UNIBUS **DECtape** DDT COMPUTER LABS IDACS CDP **EDGRIN INDACS** RAD-8 FLIP CHIP DIBOL RSX FOCAL **OMNIBUS RSTS** DECCOMM GLC-8 **EDUSYSTEM** KA10 OS/8 PHA DECsystem-10 DECpac LAB-8 DECSET **DECwriter**

SOFTWARE PERFORMANCE SUMMARY

LAB-8/E AND PDP-12 SOFTWARE SYSTEMS

DEC-Ø8-XSPSC-A-D

1.Ø	INTRODUCTION	
2.Ø	HOW TO USE YOUR SOFTWARE PERFORMANCE SUMMARY	
2.1	Introductory Section	
2.2	General Format of the Article	
2.3	Filing	
3.Ø	HOW TO COMPLETE YOUR SPR FORM (DEC 1044B-R373)	
LAB-8	/E SOFTWARE SYSTEM	
AI	OVANCED AVERAGER	
	Problem with Advanced Averager	#1
	Problem with an OS/8 Error in the RK8E DISK	# 2
	Problem with the Advanced Averager	# 3
A	JTO & CROSS CORRELATION	
	Problem with an Incorrect Value	#1
	Programming Note Concerning Batch Mode	#2
D	AQUAN MS	
	Problem with DAQUAN MS	#1
	Problem Writing the Second File to the Systems Device	# 2
	Problem with HANN Filter	#3
	Software Error	#4
PDP-1:		
	AE	
137	Software (hardware) Problem with EAE (KEl2)	#1
	COLUMNIC (MALC) ILODICM WICH DID (MALC)	
AIPOS		

MONITOR

Problem with MSORT.BIN	#1
DIAL-MS	
ASSEMBLER	
Problem with Program Location Countermentation	er Incre- #5
	π 3
CATACAL	
Patch to Correct Time vs. Amplitude	Error #1
MONITOR	
Two Bootstraps to Load LAP6-DIAL-MS from the Disk	Directly #1
DX Command Displays Block Numbers wi	ith Leading #6
SYSTEM NOTES	
Patch to Force LINCtape to be the Sy	ystem Device #1
LAP6-DIAL	
BUILD	
Disk Initialization/Blocks 470 - 47 on Disk	7 Overlaid #1
EDITOR	
Correct Usage of the LAP6-DIAL EDIT	OR #1
Problem with the Availability of Re	lays #2
FOCAL-12	
Patch to Allow FOCAL-12 to Save File Block LINCtape	es on a 1600 ₈ #1
FADC Instruction	# 2
LINC	
LINC Mode Assembling	#1
•	π1
MILDRED	
Patch to Allow Reference of Units Ø	- 77 #1
Reassembling MILDRED in Odd Numbere	d Segments #2
Patch to Allow MILDRED to Address a Block LINCtape	16ØØ ₈ #3

	Patch to Allow PIP to Save Programs on a 1600_8 Block LINCtape	# 3
	Patch to Allow PIP's "D" Option to Copy a 16008 Block LINCtape	# 2
LAB-8/E S	Software System User's Manual	#]
MASH Use:	r's Manual	# 3
AIPOS Use	er's Manual	# 3
LAP6-DIA	L-MS User's Manual	#]

1.Ø Introduction

The Software Performance Summary (SPS) is a cumulative report which provides each new software user with up-to-date information about

- o Software Problems and Solutions
- o General System Information
- o Programming Techniques

For easy reference, this document should be put in a threering notebook. Filing instructions are contained in section 2.

Each month, the articles distributed in the Digital Software News should be filed in the appropriate sections of the Software Performance Summary.

Essentially, this is your start to a maintenance document of software problems and their solutions.

Any comments or questions related to the Software Performance Summary should be directed to:

Software Communications P. O. Box F Maynard, Mass. 01754

2.Ø How to Use Your Software Performance Summary

The Software Performance Summary is intended to supplement your software and aid in its maintenance. Updates will be supplied monthly.

2.1 Introductory Section

This introductory material should be filed at the beginning of your notebook and will be referred to as chapter and paragraph numbers. To date, these are the chapters in the Introductory Section:


- 1.0 Introduction
- 2.0 How to Use Your Software Performance Summary

For example, if a new paragraph were to be inserted as the fifth paragraph of Chapter 1, the article would have a chapter and paragraph number of 1.5 (or section 1.5).

2.2 General format of the article

Each article is formatted so that you can easily recognize to what the article refers.

This is an overall example of the format. Each part will be explained in detail



(A) Title

The title of articles pertain to the Software Product Component.

B) Subtitle

This brief statement gives the reader a hint about the content of the article. The subtitle is used in the Table of Contents for identifying the problem.

(C) Problem:

A paragraph or two is used to describe the problem in general terms. It may include examples, warning, etc.

The purpose of this paragraph is to make the user aware of an existing problem in the software and its documentation.

D) Solution:

If there is a way to avoid the problem, or a patch to fix it, it is stated here.

In some articles you will find that the only solution given is "fixed in the next version".

(E) Coding

This block is used for filing purposes and is further expanded in section 2.3.

2.3 Filing

A system has been devised to help you file each article in its proper place. The key to this system is the block at the bottom of the page.

Below is a close-up view of the coding block for Systems Software.

SOF	VERS	SION	
	(1	.A)	
COMPONENT			SION
	(2	(2A)	
SUBPROGRAM OR ADDITIONAL INFORMATION			PAGE OF
(2B)			(3A)
NEW REPLACEMENT ARTICLE			AL DATE
(4) (5)			()

Each month, you should take the update and insert the pages in your notebook according to the following instructions.

First, the article is filed by Software Product (1). In this case, all articles will be classified under the major heading.

Secondly, the Software Product is broken down by its components (2).

Lastly, the article is referenced by sequence # (3). As an article is added to each component, it is assigned the next highest sequence number.

All other information in the coding block is to further clarify the article and not specifically for filing.

Explanation of all the other information included in the coding block follows:

- (1A) Version of the entire Software Product.
- (2A) Version number of components.
- (2B) If more information is necessary to help the user, it will be inserted in this block.
- (3A) This block indicates how many pages the article has.
- (4) A new article is indicated by an "X" in this block. This article has not been published before.
- (5) An article which was previously published and is being published again for reasons of revision or correction is indicated by a number in this block.

The number in the block specifies the number of times the original article has been revised.

For example: the second revision of an article which originally appeared in June, 1973 would be indicated as follows:

NEW	REPLACEMENT ARTICLE	ORIGINAL DATE
	2	June, 1973

The customer will find the date of revision #2 in the upper right corner of the article.

(5A) Original date of a revised article is placed here.

3.Ø HOW TO COMPLETE YOUR SPR FORM (DEC 1044B-R373)

In order to provide effective service and maintain comprehensive files, it is essential that the influx of information received by Software Communications be as accurate and complete as possible.

It is, therefore, extremely important that you include <u>all</u> relevant information when you submit an SPR form.

The following three pages provide information on the steps to follow when completing an SPR form. Your cooperation in this matter will help expedite improved SPR service.



Field #	

SOFTWARE PERFORMANCE REPORT

(1)	Page 1 _	of_	N	
• •	CUSTOMER			

Name				Software	Specialist	1
(3)					· · · · · · · · · · · · · · · · · · ·	
Company				Office		Cost Center
(4)			·			
Address					ort type	
(5)		·			ic/coding error	Ĭ
		Zip		_	cumentation error	
				☐ Sug	gestion (11)	
Phone		Date sent		☐ Inq		
(6) Computer		(7)	1			
Computer	System device		Memory	Other ha	dware	
(8) System program & version	(9)	10	(10)	(12)		
	on	Monitor &	version	Documen	•	Page
(13)		(14)		(15)		
<u> </u>	terminal	object 🔲	sour		☐ listing	example
(16)	printout	tape	tape)		
(17) PROBLEM STAT	EMENT:					
	-					
	·					
			· · · · · · · · · · · · · · · · · · ·			
						
(18) INITIAL FIX:						
(TO) INTITAL ETX:						
						
			· <u>· · · · · · · · · · · · · · · · · · </u>		·	
						
		· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·			
						
FOR SOFTWARE SP	ECIALIST USE ONL	Υ	FOR SOFTWAR	E COMMU	NICATIONS USE C	DNLY
DATE REC'D	TO S.C.		REC'D		TO MAINTAINER	
DATE ANS'D	TO CUSTOMER		ANS'D		TO SPECIALIST	
DATE AND D	IO COSTOMER	DAIL	U CPIA		IO SPECIALIST	

7-(360)-1044B-R373

The following is offered to assist you when processing an SPR. All blocks that are not numbered are for DEC use only. All numbered blocks should be completed by the customer as described. Typed input is recommended — if it can't be read, it can't be processed.

- (1) Each page attached should be numbered in the top right corner. N = this cover sheet plus <u>all</u> the attached pages (terminal printouts, line printer listings, etc.).
- (2) The customer should assign his record keeping number here. This number will be referenced on the acknowledgement of receipt sent out by Software Communications, thus eliminating confusion.
- (3) Name of the person at the site responsible for SPR activity. Further communications regarding the SPR will be directed to this individual.
- (4) Name of the submitting organization.
- (5) Address of the submitting organization.
- (6) Telephone number of person's name appearing in block 3.
- (7) The date sent to the DEC field office responsible for your SPR activity.

NOTE: The month should be written using letters rather than numbers, i.e., OCT.

- (8) Processor type.
- (9) If the situation being reported is related to a specific system device, list the DEC option code here.
- (10) Amount of core on your system.
- (11) The customer should check the block most appropriate to the situation.
- (12) Any information related to your system configuration that may help in diagnosing the problem.
- (13) The Software Product Component in which you feel the problem resides and its version number.

EXAMPLE: MACRO, V5A

(14) The Software Product Name and version number.

EXAMPLE: DOS-11, VØ8.02

- (15) If the problem relates to a DEC Document, insert the DEC Document number and the page(s) referred to.
- (16) Check the appropriate box. Attempt to reduce the problem to a simple test case. If you cannot, include all programs and data in some machine readable form.
- (17)* State the situation you wish to make DEC aware of.
 ----ONLY ONE PER SPR FORM----
- (18)* If a patch or way around the situation exists, include it

Forward all four copies of the SPR to the DEC office responsible for your SPR activity.

^{*} If additional space is required to present this information, USE A SECOND SPR FORM.

OS/8

Problem with Advanced Averager

PROBLEM:

The problem is applicable to the Advanced Averager for OS/8 DEC-8E-AAA2A-A-PB, DEC-8E-ALMSA-A-UB and to the Advanced Averager for paper tape DEC-8E-AAPlA-A-D. The error is in section II of the Advanced Averager. This is the section in which the data is collected. The error is that the program does not wait for an A/D conversion complete on the last channel sampled.

CORRECTION:

This can be corrected as follows for both the paper tape and OS/8 version software.

EDIT and REASSEMBLE

DELETE 6 lines ANXT through ANXT+5

INSERT Section 1

DELETE 6 lines BNXT through BNXT+5

INSERT Section 2

DELETE 14 lines of code starting with AMORE through BMORE+6

INSERT Section 3

SECTION I

ANXT,	JMS		ROU
	JMP		ANXT1
	DCA	I	BUFA
	JMP		ANXT
ANXT1,	DCA	I	BUFA

SOFTWARE PRODUCT	VERS	VERSION		
LAB-8/E SOFTWARE SYSTEM	٧1			
COMPONENT	VERS	VERSION		
ADVANCED AVERAGER	Vı	V1		
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF		
	1	1 3		
NEW REPLACEMENT ARTICLE	ORIGINA	AL DATE		

Problem with Advanced Averager (Cont'd)

SECTION 2

BNXT, JMS ROU
JMP BNXT1
DCA I BUFB
JMP BNXT

BNXT1, DCA I

BUFB

SECTION 3

ROU, Ø TAD I MPXPNT ADSK JMP .-1 SPA JMP ROU1 ADLM ADBR ADST ISZ ROU JMP I ROU ROU1, ADLM ADBR JMP I ROU

The program cannot be patched conveniently at run-time since the error is in an overlay, namely Section 2, and some of the tapes have several sections strung together. After reassembling OS/8, PIP can be used to string the binaries together as received from the program library.

If patching is desired, the OS/8 version can be patched and resaved, the paper tape version can be patched via ODT and punched as a new binary tape.

SOFTWARE PRODUCT	VERS	SION	
LAB-8/E SOFTWARE SYSTEM	Vl		
COMPONENT	VERSION		
ADVANCED AVERAGER	V1		
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF	
	1	2 3	
NEW REPLACEMENT ARTICLE X	ORIGINAL DATE		

Problem with Advanced Averager (Cont'd)

PATCHING SECTION I

LOC	OLD VALUE	NEW VALUE
7Ø21	1412	43Ø2
7Ø22	75ØØ	5225
7ø23	53Ø2	341ø
7Ø24	6531	5221
7Ø25	6533	341ø
7Ø26	3410	7ØØØ
	PATCHING	SECTION 2
7Ø6Ø	1410	43Ø2
7ø61	75øø	5264
7Ø62	5311	3411
7Ø63	6531	526Ø
7Ø64	6533	3411
7Ø65	3411	7 Ø Ø Ø
	PATCHING	SECTION 3
71Ø2	6534	ø
71Ø3	53Ø2	1412
71,04	6531	6534
71Ø5	6533	53Ø4
71Ø6	6532	751Ø
71Ø7	341Ø	5315
7110	5221	6531
7111	6534	6533
7112	5311	6532
7113	6531	23Ø2
7114	6533	57Ø2
7115	6532	6531
7116	3411	6533
7117	526Ø	57Ø2

SOFTWARE PRODUCT	VERSION	
LAB-8/E SOFTWARE SYSTEM	V1	
COMPONENT	VERSION	
ADVANCED AVERAGER	Vl	
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF
	1	3 3
NEW REPLACEMENT ARTICLE X	ORIGINAL DATE	

LAB-8/E

Problem with an OS/8 Error in the RK8E DISK

PROGRAM: DI

DEC-8E-ALMSA-A-UB DEC-8E-AAA1A-A-PB DEC-8E-AAA5A-A-PB

Advanced Averager MS

PROBLEM:

When writing a file to an RK8E DISK an OS/8 error may occur, indicating a full disk. The file can be a data file or control tape file.

CORRECTION:

Patch Section 1 of Advanced Averager MS in field 1

LOC	NEW VALUE	
12213	71Ø1	IAC CLL
12215	743Ø	SZL
12216	5352	JMP 12352
12352	744Ø	SZA
12353	5221	JMP ERR
12354	5217	JMP 12217

Patch Section 5 of Advanced Averager MS in field Ø

LOC NEW VALUE

6714 71Ø1 IAC CLL

SOFTWARE PRODUCT	VERSION	
LAB-8/E SOFTWARE SYSTEM	V1	
COMPONENT	VERSION	
ADVANCED AVERAGER MS	V	'1
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF
	2	1 2
NEW REPLACEMENT ARTICLE X	ORIGINAL DATE	

Problem with an OS/8 Error in the RK8E DISK (Cont'd)

6716 6717 672Ø 6721	743Ø 5332 3764 7ØØØ		6732 WANSA
6732 6733	764Ø 5763	SZA	
6734	5 7 6 3 5 3 2 Ø		ERROR 672Ø

SOFTWARE PRODUCT	VERSION		
LAB-8/E SOFTWARE SYSTEM	Vl		
COMPONENT	VERSION		
ADVANCED AVERAGER MS	Vl		
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF	
	2	2 2	
NEW REPLACEMENT ARTICLE	ORIGINAL DATE		

LAB 8/E

Problem with the Advanced Averager

PROBLEM:

This program will fail when TRIGGER is entered if in Section I the channels are selected so that they store the data block links over the trigger section (4272-4365 of field Ø). A three word link is stored in core at the end of each data block. If the channels are selected so that the end of the data block is in the same core locations as TRIGGER, the end of the block link will be stored over the trigger section.

SOLUTION:

To avoid this problem, create a CONTROL TAPE and run from it.

This article was originally coded as Component - AVERAGER-8, Sequence #1.

SOFTWARE PRODUCT		SION
LAB-8/E SOFTWARE SYSTEM		
COMPONENT	VERSION	
ADVANCED AVERAGER		
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF
	3	1 1
NEW REPLACEMENT ARTICLE X	ORIGINA	AL DATE

OS/8-LAB-8/E and LAB-8/E

Problem with an Incorrect Value

PROGRAM: Auto and Cross Correlation

DEC-LB-U41B-PB DEC-8E-AACRA-A-PB DEC-8E-ALMSA-A-UB

PROBLEM:

There is an incorrect value in a table at location 7363.

CORRECTION:

The decimal value should be 45.

PATCH: Store 55 at location 7363.

SOFTWARE PRODUCT	VERSION	
LAB-8/E SOFTWARE SYSTEM	V1.	
COMPONENT	VERS	SION
AUTO & CROSS CORRELATION	V	1
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF
	1	1 1
NEW REPLACEMENT ARTICLE X	ORIGINA	AL DATE

LAB-8E AUTO CORRELATION (DEC-LB-U41B-PB)

Programming note concerning batch mode

PROBLEM:

User's should be aware that the program may "hang up" in batch mode if the sampling rate is too fast.

SOLUTION:

This problem will be corrected in the next revision which will be announced in the newsletter.

This article was originally coded as Component - CORR-8, Sequence #1

SOFTWARE PRODUCT	VERSION	
LAB-8/E SOFTWARE SYSTEM		
COMPONENT	VERSION	
AUTO & CROSS CORRELATION		
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE # PAGE OF	
	2	1 1
NEW REPLACEMENT ARTICLE	ORIGINA	AL DATE
x		

OS/8 LAB-8/E

Problem with DAQUAN MS

The program DAQUAN MS DEC-8E-ADAQA on paper tape and DEC-8E-ALMSA-A-UB on DECtape, swaps page 7600 of field #l into field 0 so that it can have all of field #l while running under OS/8. However, it will destroy the data in DAQUAN channel 2 if an MA command is given to read or write a file.

To avoid this the following change can be made:

REASSEMBLING TO CORRECT PAGE 7600 OF FIELD #1 SWAPPING PROBLEM FOR DAQUAN MS

ØØ2ØØ	JMS	M76TF1
Ø2242	JMS	M76TF1
Ø2453	JMS	M76TF1
Ø2527	JMS	M76TF1
Ø2536	SZA	CLA
Ø3746	SZA	CLA

DELETE M76TF1 through and including M76LOK. INSERT above and following CODE to fix page 7600 swapping problem. To patch, insert the following:

PATCH AND REASSEMBLE TO CORRECT PAGE 7600 OF FIELD #1
SWAPPING ERROR IN DAQUAN MS. Change field 0 as follows:

2336	ø	M76TF1,	ø	
2337	72ØØ		CLA	
234Ø	1364		TAD	M76LOK
2341	7ø4ø		CMA	
2342	3364		DCA	M76LOK
2343	1361		TAD	(76øø
2344	3132		DCA	TEMP1
2345	1362		TAD	(PS76ØØ
2346	3133		DCA	TEM2
2347	1361		TAD	(-2ØØ

NEW	REPLAC EMENT ARTICLE	ORIGIN	AL DATE	
		1	1 3	
SUBPROGRAM	OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF	
	DAQUAN MS	v	1	
	COMPONENT	VER	VERSION	
LAB-8	3/E SOFTWARE SYSTEM	V	V1	
SOFTWARE PRODUCT VERSION		SION		

Problem with DAQUAN MS (Cont'd)

235Ø	3131		DCA	TEMP
2351	62Ø1	M76Tl,	CDF	ø
2352	1533		TAD I	TEM2
2353	3Ø13		DCA	AUTO
2354	5763		JMP	(24ØØ
2355	5736	M76T2,	JMP I	M76TF1
		M76LOK,	Ø	

Change field Ø as follows:

		*24ØØ	
24ØØ	6211	CDF	1Ø
24Ø1	1532	TAD I	TEMP1
24Ø2	62Ø1	CDF	ø
24Ø3	3533	DCA I	TEM2
2494	1Ø13	TAD	AUTO
24Ø5	6211	CDF	1 Ø
24Ø6	3532	DCA I	TEMP1
24Ø7	2132	ISZ	TEMPl
241Ø	2133	ISZ	TEM2
2411	2131	ISZ	TEMP
2412	5616	JMP	(M76Tl
2413	62 Ø 1	CDF	Ø
2414	5615	JMP	(M76T2
2415	2355		
2416	2351		

PATCH TO CORRECT 7600 OF FIELD #1 SWAPPING ERROR IN DAQUAN MS. Change field 0 as follows:

Ø2362 Ø2363 Ø2364	26 \vec{g}{\vec{g}} \qquad \qqquad \qqqqq \qqqqq \qqqqq \qqqqqqqqqqqqqqq	s for M76TFl Routine
Ø2535 Ø2536 Ø2562	1762 7640 — Refere 2364	ences to M76LOK
Ø3777 Ø3764	2364 76 <u>4</u> Ø	

SOFTWARE PRODUCT	VERS	VERSION		
LAB-8/E SOFTWARE SYSTEM	Vl			
COMPONENT	VERSION			
DAQUAN MS	Vl			
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF		
	1	2 3		
NEW REPLACEMENT ARTICLE X	ORIGINAL DATE			

Problem with DAQUAN MS (Cont'd)

ØØ377	2336			
Ø2242	4336	Calle	+0	M76TFØ
Ø2453	4764	Calls	LU	M/OIFØ
Ø2527	4764			

SOFTWARE PRODUCT	VERSION		
LAB-8/E SOFTWARE SYSTEM	V1		
COMPONENT VERSION		SION	
DAQUAN MS	V1		
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF	
1 3			
NEW REPLACEMENT ARTICLE	ORIGINAL DATE		

OS/8 LAB-8/E

Problem Writing the Second File to the Systems Device

PROBLEM:

The programs:

DAQUAN MS

DEC-8E-ADAQA

DAQUAN MS

DEC-8E-ALMSA-A-UB

have an error when trying to write the second file to the systems device.

SOLUTION:

The following patch will correct the problem:

PATCH TO CORRECT FILE WRITING ERROR IN DAQUAN, MS, DAFFT, PAFFT. Change field Ø as follows:

Ø224Ø	5356	JMP 2356	
Ø2356	136Ø	TAD (MSFN	
2357	5773	JMP 256Ø	
236Ø	2531	•	
Ø2373	256Ø		
Ø256Ø	3246	DCA MASSA4	
2561	5241	JMP MASS1	

REASSEMBLE TO CORRECT FILE WRITING ERROR IN DAQUAN MS

In field \emptyset , before the line with tag MASS8 insert,

TAD (MSFN DCA MASSA4

SOFTWARE PRODUCT	VERSION		
LAB-8/E SOFTWARE SYSTEM	V1		
COMPONENT	VERSION		
DAQUAN MS	V1		
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF	
	2	1 1	
NEW REPLACEMENT ARTICLE	ORIGINAL DATE		

OS/8

Problem with HANN Filter

PROBLEM:

The HANN Filter in both DAFFT (DEC-8E-ADAFA) or (DEC-8E-ALMSA-A-UB) and PAFFT (DEC-8E-APAFA) or (DEC-8E-ALMSA-A-UB) are both incorrect.

SOLUTION:

To correct the OS/8 "SAVED" image of DAFFT and PAFFT: it can be patched or the sources of DAFFT and PAFFT can be reassembled and then SAVED. To patch the HANM routine it must be changed and references to the tag INST in DAFFT and to INST and HANM in PAFFT must be changed. To reassemble, the HANM routine need only be changed.

HANN Filter is as follows for points $(\emptyset$ -N)

$$\hat{G}_{o} = 1/2G_{o} + 1/2G_{1}$$

$$\hat{G}_{i} = -1/4G_{i-1} + 1/2G_{i} - 1/4G_{i+1}$$

$$\hat{G}_{n} = 1/2G_{n-1} + 1/2G_{n}$$
 $i=1,2,...,n-1$

where \hat{G} are the output points of the filter and G are the original points passed through the filter.

This is the HANN Filter ALGORITHM

SOFTWARE PRODUCT	VERSION		
LAB-8/E SOFTWARE SYSTEM	Vl		
COMPONENT	Version		
DAQUAN MS	v	1	
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE	
		OF	
DAFFT/PAFFT	3		

```
Ø
         DCA TMPX / 1/2Y (I)
         TAD I 13 / get 2nd pt
         ASR
         Ø
         DCA TMPY / 1/2Y (I+1)
         TAD TMPY
         JMP INST+1 / go set 1st pt = 1/2 (1st + 2nd)
         TAD I 13 / get Y (I+1)
SMGO,
         ASR
         Ø
                  / 1/2 (I+1)
         DCA TMPY
          TAD TMPY
         ASR
                    / AC=1/4Y (I+1)
                    / + 1/4Y (I-1)
         TAD TMP
                    / NO P if 3 pt filter; CIA if HANN
         CIA
INST,
                    / +1/2Y (I)
         TAD TMPX
                    / store as Y (I)
          DCA I 14
          TAD TMPX
                    / set up for next pt:
          ASR
                    / new 1/4Y (I-1)
          DCA TMP
                    / done next to last pt?
          ISZ CNT
          SKP
                    / no
                    / yes
          JMP .+4
          TAD TMPY
          DCA TMPX
                    / new 1/2Y (I)
          JMP SMGO
                    / add 1/2(Y(N-1) + (N))
          TAD TMPX
          TAD TMPY
                    / store as last pt
          DCA I 14
          JMP I HANM
          TMPY, Ø
```

SOFTWARE PRODUCT	VERS	VERSION		
LAB-8/E SOFTWARE SYSTEM	V1			
COMPONENT	Vers	Version		
DAQUAN MS	V1	V1		
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE		
DAFFT/PAFFT	3	OF 2 6		
NEW REPLACEMENT ARTICLE X	ORIGINAL DATE			

Change field 1 as follows:

DAFFT

ADD	PATCH VALUE		REASSEMBLE
223	7447		SWBA
224	2252		ISZ CNT
225	1413		TAD I 13
226	7415		ASR
227	Ø		ø
230	3254		DCA TMPX
231	1413		TAD I 13
232	7415		ASR
233	ø		Ø
234	3356		DCA TMPY
235	1356		TAD TMPY
236	525Ø		JMP INST+1
237	1413	SMGO,	TAD I 13
240	7415		ASR
241	Ø		Ø
242	3356		DCA TMPY
243	1356		TAD TMPY
244	7415		ASR
245	Ø		Ø
246	1253		TAD TMP
247	7041	INST,	
	5336		JMP 1Ø336
2 5 Ø	3330		<i>p</i>

SOFTWARE PRODUCT			VERSION		
LAB-8/E SOFTWARE SYSTEM			٧ı		
COMPONENT			Version		
daquan ms			V1		
SUBPROGRAM OR ADDITIONAL INFORMATION		SEQUENCE #	PAG OF	_	
DAFFT/PAFFT			3	3	6
NEW REPLACEMENT ARTICLE			ORIGINA	AL DATE	
х					

Change field 1 as follows:

DAFFT

ADD	PATCH VALUE	REASSEMBLE
336	1254	TAD TMPX
337	3414	DCA I 14
34Ø	1254	TAD TMPX
341	7415	ASR
342	ø	Ø
343	3253	DCA TMP
344	2252	ISZ CNT
345	741Ø	SKP
346	5352	JMP .+4
347	1356	TAD TMPY
35Ø	3254	DCA TMPX
351	5237	JMP SMGO
352	1254	TAD TMPX
353	1356	TAD TMPY
354	3414	DCA I 14
355	5621	JMP I HANM
356	Ø TMPY,	ø

DAFFT / FOR PATCH ONLY

ADD	VALUE
ØØ546	247
10212	3247

SOFTWARE PRODUCT		VER	VERSION	
LAB-8/E SOFTWARE SYSTEM		V	٧ı	
COMPONENT		Vers	Version	
DAQUAN MS		V	V1	
SUBPROGRAM	SUBPROGRAM OR ADDITIONAL INFORMATION		1	GE OF
	3	4	6	
NEW X	REPLACEMENT ARTICLE ORIGINAL DATE			

Change field 1 as follows: PAFFT

ADD	PATCH VALUE		REASSEMBLE
314 315 316 317 320 321 322 323 324 325 326	Ø 4113 7447 21Ø7 1413 7415 Ø 3111 1413 7415	HANM,	Ø JMS PSTR SWBA ISZ CNT TAD I 13 ASR Ø DCA TMPX TAD I 13 ASR
327 330 331 332 333 334 335 336 337 340	3363 1363 5343 1413 7415 Ø 3363 1363 7415	SMGO,	DCA TMPY TAD TMPY JMP INST+1 TAD I 13 ASR Ø DCA TMPY TAD TMPY ASR Ø
341 342 343 344 345 346 347 350 351 352 353 354 355 356 357 360 361 362 363	1110 7041 1111 3414 1111 7415 0 3110 2107 7410 5356 1363 3111 5332 1111 1363 3414 5714	INST,	TAD TMP CIA TAD TMPX DCA I 14 TAD TMPX ASR Ø DCA TMP ISZ CNT SKP JMP .+4 TAD TMPY DCA TMPY DCA TMPX JMP SMGO TAD TMPX TAD TMPY DCA I 14 JMP I HANM Ø

SOFTWARE PRODUCT	VERSION	
LAB-8/E SOFTWARE SYSTEM	Δ	1
COMPONENT	Version	
DAQUAN MS	٧1	
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF
DAFFT/PAFFT	3	5 6
NEW REPLACEMENT ARTICLE X	REPLACEMENT ARTICLE ORIGINAL DATE	

PAFFT / FOR PATCH ONLY

	,	
ADD	PATCH VALUE	
ØØ541	342	
1Ø212 1Ø226	3342 3342	
1Ø214 1Ø215	4314 4314	
10230 10231	4314 4314	

SOFTWARE PRODUCT	VERSION		
LAB-8/E SOFTWARE SYSTEM	V1		
COMPONENT	Version		
DAQUAN MS	٧ı	Vl	
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE # PAGE OF	,,,,,,,	
DAFFT/PAFFT	3 6	6	
NEW REPLACEMENT ARTICLE X	ORIGINAL DATE		

OS/8 LAB-8/E

Software Error

PROGRAM: DAQUAN MS DAFFT DEC-8E-ADAQA-A

DEC-8E-ADAFA-A

DAQUAN MS PAFFT DEC-8E-ADAQA-A

DEC-8E-APAFA-A

These programs are also on DECtape DEC-8E-ALMSA-A-UB.

PROBLEM:

There is a software error in DAQUAN MS DAFFT and PAFFT when using hardware EAE.

CORRECTION:

Insert an SWBA (7447) at the following locations in field \emptyset and reassemble.

- A. Between "CALL FLIN" and "TAD INPSW" at 602.
- B. Between "JMS I .+2" and "JMP I FOUTX" at 765.
- C. Between "CALL FPNORM" and "JMP I FLOATR" at 2554.

SOFTWARE PRODUCT		VER	SION
LAB-8/E S	OFTWARE SYSTEM	Vl	
	COMPONENT	Vers	ion
DAQUAN	MS	٧ı	
SUBPROGRA	M OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF
	DAFFT/PAFFT		1 2
NEW X	REPLACEMENT ARTICLE	ORIGINAL DATE	

Software Error (Cont'd)

TO PATCH: change the following locations in field \emptyset .

<u>LOC</u>	OLD VALUE	NEW VALUE
6 Ø 2	1Ø52	537Ø
764	4766	4767
765	5762	7447
766	56ØØ	5762
767		56Ø Ø
77Ø		7447
771		1Ø52
772		52Ø3
2553	4755	4757
2554	5744	7447
255 5	7265	5744
2556	ØØ13	ØØ13
2557		7265

SOFTWARE PRODUCT		VERS	VERSION	
LAB-8/E SOFTWARE SYSTEM V1		1		
	COMPONENT	VERSION		
DAQUA	DAQUAN MS		V1	
SUBPROGRAM	SUBPROGRAM OR ADDITIONAL INFORMATION		PAG OF	_
DAFFT/PAFFT		4	2	2
NEW REPLACEMENT ARTICLE X		ORIGINA	AL DATE	

PDP-12

Software (hardware) problem with EAE (KE12)

PROBLEM:

The instructions CLA (7601) and NMI (7411) are defined as being micro programmable, but due to a hardware problem they do not function properly when micro programmed.

SOLUTION:

Therefore, the instructions CLA and NMI should be used as two separate instructions. No correction is planned for the hardware.

SOFTWARE PRODUCT	VERSION	
PDP-12		
COMPONENT	VERSION	
EAE		
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE # PAGE OF	
CLA and NMI INSTRUCTIONS	1 1 1	
NEW REPLACEMENT ARTICLE	ORIGINAL DATE	
Х		

,			

AIPOS MONITOR

Problem on RUBOUT

PROBLEM:

In the AIPOS Monitor on RUBOUT, the command interpreter sometimes stores information in the wrong file descriptor block.

SOLUTION:

To correct this problem, the following binary patch should be implemented.

Block 1 (add 1 to the starting block) of JOB CONTROL:

LOCATION	OLD CONTENTS	NEW CONTENTS	
224	7ØØ1	7ØØØ	

To implement a source patch, CMØ2, line 417 [IAC] should be deleted. The segment of the source should now read:

TAD I P1FAUX AND P7 IAC DCA FILCNT JMP CMI18Ø

SOFTWARE PRODUCT	VERSION		
AIPOS			
COMPONENT	VERSION		
MONITOR			
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE # PAGE OF		_
	1	1	1
NEW REPLACEMENT ARTICLE	ORIGINA	AL DATE	
х			

AIPOS

Problem with MSORT.BIN

PROBLEM:

If certain conditions occur at MIDAS time (data acquisition), MSORT will fail to sort some runs. As a result, the user will lose his data. The problem is in MSORT, not MIDAS. The data is really in the MIDAS file, but MSORT cannot find it. The problem occurs when a user issues the full 21 runs allowed between resets. Up until the next reset, all runs subsequent to this condition are not sortable. This could be as many as 21 lost experiments.

SOLUTION:

The solution is to either make the following patch to MSORT.BIN or issue resets before 21 runs.

WARNING: It is unwise to attempt a patch without having a backup of the binary to be patched.

To make the patch, use the JCL display index command to get the starting block of MSORT.BIN. Add 3 to it to get the block to be patched; e.g., if MSORT.BIN starts at block 273 then the block to be patched is 273+3=276. The programs PATCH or TED can be used to effect the patch, or the console can be used directly to read in the block, modify it, and write it back out (LINCtape file only).

To check the patch, load the MSORT program via JCL. Halt the CPU and examine the core locaitons indicated to see if the new values are there.

SOFTWARE PRODUCT		VERS	VERSION	
AIPOS				
	COMPONENT	VERS	VERSION	
MS	MSORT.BIN			
SUBPROGRAM	SUBPROGRAM OR ADDITIONAL INFORMATION		PA(O	
		1	1	2
NEW X	REPLACEMENT ARTICLE	ORIGINA	AL DATE	

Problem with MSORT.BIN (Cont'd)

PATCH TO MSORT.BIN

Core Location	Location in Patch Block	Old Contents	New Contents
3676	276	764ø	5344
•	•	•	•
•	•	•	•
3744 3745 3746 3747	344 345 346 347	Ø Ø Ø	764Ø 53Ø7 1ØØ2 53Ø5

SOFTWARE PRODUCT	VERSION		
AIPOS	AIPOS		
COMPONENT	VERSION		
MSORT.BIN			
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF	
	1	2 2	
NEW REPLACEMENT ARTICLE X	ORIGINAL DATE		

DIAL-MS ASSEMBLER

Problem with program location counter incrementation

DIAL-MS Assembler increments the program location counter with an ISE instruction, which does not provide for the case where the last location is 7777. The assembler will then skip when the counter is incremented. This creates a problem for programs which wrap around memory, i.e., from location 7777 to $\emptyset\emptyset\emptyset$. The skip causes the page indicator not to be reset, which prevents detection of illegal memory references from page \emptyset to page 37. The patch given below will correct this.

PATCH TO DIAL-MS ASSEMBLER:

BLOCK	LOCATION	OLD CONTENTS	NEW CONTENTS
333	Ø41	2Ø3Ø	5642
333	Ø42	1Ø37	1761
333	361	×	2Ø3Ø
333	362	x	7ØØØ
333	363	X	1Ø37
333	364	X	5765
333	365	X	1443

SOFTWARE PRODUCT		VERS	SION
DIAL-			
COM	PONENT	VERS	SION
AS SEMB	LER		
SUBPROGRAM OR AI	SUBPROGRAM OR ADDITIONAL INFORMATION		PAGE OF
		5	1 1
NEW X	REPLACEMENT ARTICLE	ORIGINA	AL DATE

CATACAL

Patch to correct time vs. amplitude error

PROBLEM:

A problem exists concerning incorrect amplitude scaling in the averager as a function of sample rate.

CATACAL uses "window" or "boxcar" averaging and scales down the sum by an appropriate power of two determined by sample rate. However, in the region of 10 to 1 points per second, there is a problem which effectively divides the data by an extra power of two so the results are half-sized.

SOLUTION:

This is corrected by assembling the following patch and doing an ADD BINARY under DIAL-MS to current CATACAL binary.

Two other small corrections are also included in the patch:

- Removing Y axis cursor "fudge" factor.
- 2. A small change to integer float routine to guarantee that the entire FAC and overflow word are correctly set up before normalizing it.

SOF	TWARE PRODUCT DIAL-MS	VERS	VERSION	
	COMPONENT CATACAL	Vers	ion	
SUBPROGRAM C	OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF 1 2	
NEW X	REPLACEMENT ARTICLE	ORIGINA	AL DATE	

/PATCH FOR CATACAL TO CORRECT FOR /TIME VS AMPLITUDE ERROR, 7/23/72

336Ø 4Ø57 ØØØ3	7ØØØ 44Ø3 457Ø	PMODE FLOATR=56Ø *336Ø NOP *4Ø57 JMS I 3 *3 PATCH1	/NO Y FUDGE ON CURSORS
457Ø 4571 4572 4573 4574 4575 4576	ØØØØ PATCH1, 1121 71Ø4 771Ø 724Ø 1Ø44 577Ø	TAD121 CLL RAL SPA CLA STA TAD 44	/LESS THAN 4000 (8) SAMPLES/PT? /YES, DECR, FOR SHIFT CT /GET EXP AS SHIFT CT /AND EXIT WITH CT IN AC /IS SCR INSTR
Ø565 Ø566 Ø567 Ø576	3Ø47 4776 576Ø 66ØØ	*FLOATR+5 DCA 47 JMS I 576 JMP I FLOATR *576 6600	/CLEAR OVERFLOW WORD, TOO

LISTAP-7

SOF	TWARE PRODUCT DIAL-MS	VERS	SION
	COMPONENT	Vers	ion
	CATACAL		
SUBPROGRAM	SUBPROGRAM OR ADDITIONAL INFORMATION		PAGE 2 OF 2
NEW	REPLACEMENT ARTICLE	ORIGINA	AL DATE

LAP6-DIAL-MS

Two bootstraps to load LAP6-DIAL-MS directly from the disk

The following two bootstraps should be used to load LAP6-DIAL-MS directly from the disk (RFØ8 or RKØ8). Each bootstrap when assembled, will yield one block of binary that must be moved to block Ø of the respective disk via PDP-12 PIP. The following instructions should be followed to assemble the bootstrap needed:

- 1. Type up the program via LAP6-DIAL EDITOR
- →ZE (zero binary work area)
- 3. →AS (assemble program)
- 4. →SB (save binary of program)
- 5. →DX (note where the one block of binary is saved)
- 6. \rightarrow PIP*(load PIP and transfer the one block of binary to RIØ (disk Ø), block Ø)
- 7. Toggle in the two or four word bootstrap and LAP6-DIAL-MS will start up.
- *After the PIP transfer, the user should create an index entry (via PDP-12 TED) in the DIAL index so that DIAL will not save a file over this binary.

The procedure above assumes that the disk has been initialized See LAP6-DIAL Manual, DEC-12-SE2D-D; Appendix A, section A.3.

so	SOFTWARE PRODUCT DIAL-MS		SION
	COMPONENT MONITOR		ion
SUBPROGRAM	SUBPROGRAM OR ADDITIONAL INFORMATION		PAGE OF 4
NEW X	REPLACEMENT ARTICLE	ORIGINA	AL DATE

```
*20
```

øø2ø

ØØ21

ØØ22

ØØ23

ØØ24

ØØ25

ØØ26

6623

5Ø2Ø

1Ø44

3445

1044

3446

1041

```
Pre-1973
           PMODE
           *2Ø
/RFØ8 BOOTSTRAP FOR DIAL-MS
/COPYRIGHT 1971
/DIGITAL EQUIPMENT CORPORATION
/MAYNARD, MASS. Ø1754
/7/14/71
/SGW
/FIRST, ASSEMBLE THE PROGRAM BELOW AND MOVE THE
/BINARY TO BLOCK Ø OF UNIT 1Ø (RFØ8 DISK).
/TO PRESERVE BLOCK ZERO, IT MAY BE WISE TO FAKE
/AN ENTRY IN THE INDEX OF UNIT 10 SHOWING
/BLOCK Ø AS USED, SO THAT SOMETHING DOESN'T
/GET SAVED THERE AND DESTROY THE BOOTSTRAP.
/THEN,
/TO USE:
/TOGGLE IN THE FOLLOWING:
        *2Ø
                 /PMODE
        66Ø3
                 /READ
                 /JMP ,
        5Ø21
        *775Ø
        7577
                 /WORD COUNT-1
        7777
                 /CORE LOC-1
/SET MODE = PMODE
/I/O PRESET
/START 20
        DISK
                        /THIS OVERLAYS THE 6603
        JMP
                 .-1
                        /AND THIS OVERLAYS THE JMP.
        TAD
                 P6777
        DCA I
                 P775Ø
                        /LOAD WORD COUNT-1
        TAD
                 P6777
        DCA I
                 P7751
                        /AND ADDRESS-1
        TAD
                 P1Ø
```

SOFTWARE PRODUCT VERSION		SION		
DI	AL-MS			
COM	PONENT	Version		
МС	ONITOR			
SUBPROGRAM OR ADDITIONAL INFORMATION		SEQUENCE #	PAGE	
		1	2 OF 4	
NEW	REPLACEMENT ARTICLE	ORIGINA	ORIGINAL DATE	
X				

```
Pre-1973
```

```
/LOAD EXTENDED ADDRESS (FIELD 1)
ØØ27
       6615
                      DIML
                                       /THIS IS BLOCK 322 IN DISGUISE
                                P15
       1042
                      TAD
ØØ3Ø
ØØ31
       6643
                      DXAL
                                       /...MORE OF BLOCK 322
                                Pløøø
       1043
                      TAD
ØØ32
                                       /READ
ØØ33
       66Ø3
                      66Ø3
                                       /SKIP ON DONE
                      DISK
ØØ34
       6623
                      JMP
                                .-1
ØØ35
       5Ø34
       6213
                      CIF CDF
                                10
ØØ36
                      JMP I
                                .+1
ØØ37
       544Ø
                                       /BOOT DIAL NOW
                      7777
ØØ4Ø
       7777
            PlØ,
                      10
ØØ41
       gg1g
                      15
ØØ42
       ØØ15
              P15,
                      1ØØØ
              Pløøø,
ØØ43
       1ØØØ
ØØ44
       6777
              P6777,
                      6777
                       775Ø
ØØ45
       775Ø
              P775Ø,
9946
       7751
              P7751,
                      7751
                      DXAL=6643
                      DIML=6615
                      DISK=6623
              *20
              /RKØ8 BOOTSTRAP FOR DIAL-MS
              /COPYRIGHT 1971
              /DIGITAL EQUIPMENT CORPORATION
              /MAYNARD, MASS. Ø1754
              /FIRST, ASSEMBLE THE PROGRAM BELOW AND MOVE
              /THE BINARY TO BLOCK Ø OF UNIT 10 (RKØ8 DISK).
              /IT MAY BE WISE TO FAKE AN ENTRY IN THE INDEX
              /OF UNIT 10 TO PROTECT BLOCK 0 SO THE BOOTSTRAP
              /DOESN'T GET DESTROYED.
              /TO USE:
              /TOGGLE IN THE FOLLOWING:
                      *2Ø
                                /PMODE
                      6733
                                /READ
              /
                      5Ø21
                                /JMP
              /SET PMODE
              /I/O PRESET
              /START 2Ø
              /THE PROGRAM BELOW IS ORIGINED AT *17, BUT IT ACTUALLY
              /GETS LOADED AT *20, WHICH IS WHY ALL THE REFERENCES
              /ARE OFF BY 1.
```

SOFTWARE PRODUCT	VERS	SION	
DIAL-MS			
COMPONENT	Vers	ion	
MONITOR			
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF 4	
NEW REPLACEMENT ARTICLE X	ORIGINA	ORIGINAL DATE	

0Ø17	6745		PMODE *17 DSKD		/SKIP	DISE	done	(OVERLAY	S THE
øø2ø	5Ø2Ø		J M P	1+1	/THIS	IS F		6733) JMP ,-1 AYS THE J	
ØØ21	1Ø4Ø		TAD	P1Ø+1			112	ALS THE U	MF /
øø22	6732		DLDC	,	/FIELI) 1			
ØØ23	1041		TAD	P6777+			ADDR.	-1	
ØØ24	6755		DLCA		-,			_	
ØØ25	1Ø42		TAD	P7ØØØ+	L/WORD	COUN	T		
ØØ26	6753		DLWC		•				
ØØ27	6742		DCLS						
øø3ø	1Ø43		TAD	P322+1					
ØØ31	6733		DLDR		/READ	BLOC	CK 322		
ØØ32	6745		DSKD						
ØØ33	5Ø33		JMP	1+1					
ØØ34	6213		CIF CDF	10					
ØØ35	5437		JMP I	.+1+1	/BOOT	DIAL	NOM		
ØØ36	7777		7777						
ØØ37	øølø	PlØ,	1Ø						
øø4ø	6777	P6777,	6777						
ØØ41	7ØØØ	P7ØØØ,	7ØØØ						
ØØ42	Ø322	P322,	322	_					
			DSKD=6745						
			DLDC=6732						
			DLCA=6755 DLWC=6753	-					
			DCLS=6742	~					
			DLDR=6733						
				•					

	SOFTWARE PRODUCT DIAL-MS		BION	
	COMPONENT MONITOR		ion	
SUBPROGRAM C	SUBPROGRAM OR ADDITIONAL INFORMATION		PAGE 4 OF 4	
NEW X	REPLACEMENT ARTICLE	ORIGINA	ORIGINAL DATE	

DIAL-MS

DX command displays block numbers with leading zeroes out of line

The PXDXSRC program adds an incorrect value to the horizontal coordinate of the index display when it skips leading zeroes. The patch below will correct the problem.

PATCH TO LAP-6 DIAL-MS TAPE:

Block	Location	Old Contents	New Contents
362	267	ØØ12	ØØ14

SOFTWARE PRODUCT	VERSION	
DIAL-MS		i
COMPONENT	VERSION	
MONITOR		
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE OF
	6	1 1
NEW REPLACEMENT ARTICLE X	ORIGINAL DATE	

DIAL-MS

Patch to force LINCtape to be the system device

PROBLEM:

There are a number of occasions when it is desirable that DIAL-MS does not use a disk as the system device, even though one is present on the system. Among these instances are the following cases:

- Using the FPP Assembler on a system with one DF-32 disk: the Assembler requires DIAL-MA, but also requires that if DF-32's are used as the system device, at least two must be present.
- 2. Using FOCAL-12 under these same circumstances.
- 3. Initializing a tape on a system with an inoperable or malfunctioning disk.
- 4. Starting up DIAL-MS on a system in which the disk must not be overwritten, e.g., in a CL-12 or PS/12 situation.

SOLUTION:

The following patch to the DIAL-MS system tape solves this problem by allowing sense switch \emptyset to affect the choice of a system device. If SS \emptyset is in the \emptyset position, DIAL-MS is initialized in the same manner as it currently is. If SS \emptyset is in the 1 position at the time of initialization, however, LINCtape will be chosen as the system device regardless of what disks are present on the system.

BLOCK	REL. LOCN.	OLD VALUE	NEW VALUE
31ø	Ø14	Ø	Ø44Ø
31ø	Ø15	ø	6ø36
31ø	ø 16	ø	øøø2
31 ø	ø17	ø	5766
31 ø	Ø35	øø11	6014

SOF	SOFTWARE PRODUCT DIAL-MS		SION
SYS	COMPONENT SYSTEM NOTES		ion
SUBPROGRAM	SUBPROGRAM OR ADDITIONAL INFORMATION		PAGE 1 OF 1
NEW X	REPLACEMENT ARTICLE	ORIGINA	AL DATE

LAP6-DIAL BUILD

Disk initialization/blocks 47% - 477 overlaid on disk

PROBLEM:

LAP6-DIAL will copy blocks 300 to 477 from LINCtape to disk whenever the disk is initialized, i.e. LS=0701; RS=7310; I/O Preset; DO; Start 20. This will result in block 470 to 477, usually reserved for file area, to be overlaid by whatever is contained in blocks 470 to 477 on the LINCtape.

SOLUTION:

The following patch will correct this problem. In the source (BUILD DEC-12-ZR5B):

LINE NUMBER	FROM	TO
Ø674	BM2Ø, -2Ø	BM2Ø, -17

On a LAP6-DIAL System tape:

TAPE BLOCK	WORD	FROM	TO
31Ø	373	776Ø	7761

	TWARE PRODUCT LAP6-DIAL	VERSION		
	COMPONENT BUILD	Vers	ion	
SUBPROGRAM	OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE 1 OF 1	
NEW X	REPLACEMENT ARTICLE	ORIGINA	ORIGINAL DATE	

Correct usage of the LAP6-DIAL EDITOR

PROBLEM:

While working with LAP6-DIAL Editor, the user may experience problems if he encounters the following situation:

4Ø36	/THIS IS THE 100th BLOCK	BLOCK
4Ø37	/THIS IS THE LAST LINE	1ØØ
4040	/THIS IS THE FIRST LINE IN BLOCK 1Ø1	BLOCK 1Ø1

Assume there are four spaces after 1 in 101. By moving the cursor back using knob 3 to anywhere on the line and pressing a return, line 4040 up to the cursor will be stored (written) onto block 470.

The same procedure will work if you are at line 7777, except the next thing viewed on the scope is line 1 and the entire working area is destroyed.

SOLUTION:

 $\frac{DO}{in}$ turn the cursor back and strike a carriage return $\frac{DO}{in}$ the middle of a line whenever there is a 100 block source program in the working area (or when at line 7777).

This problem has been corrected in the LAP6-DIAL-MS Version 2. However, it will not be corrected in the LAP6-DIAL-V2 System Editor that goes out on that same tape (DEC-12-SE2A-UO).

SOFTWARE PRODUCT LAP6-DIAL	VERSION	
COMPONENT EDITOR	Vers	ion
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE 1 OF 1
NEW REPLACEMENT ARTICLE X	ORIGINAL DATE	

EDITOR

Problem with the availability of relays

PROBLEM:

The LAP6-DIAL V2 EDITOR checks the availability of the relays, to determine whether to use the analog potientiometers in the Editor.

ALTERNATE SOLUTION:

To get around this, the following patch should be used:

- 1. Load block 312 into core via Ø7ØØ Ø312; I/O preset: DO
- Change LINC location 4046 from 7650 to 7200
- 3. Rewrite back onto tape block 312 via Ø7Ø4

NOTE: For PDP-12 B 1/2 user's (A-D's, no relays)

SOFTWARE PRODUCT LAP6-DIAL	VERSION	
COMPONENT EDITOR	Version	
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE 1 OF 1
NEW REPLACEMENT ARTICLE	ORIGINAL DATE	

FOCAL-12

Patch to allow FOCAL-12 to save files on a 1600 Block LINCtape

To allow FOCAL-12 (on LINCtape DEC-12-SE2E-UO) to save files on a 1600_8 block LINCtape, make the following changes to the binary.

FOCAL-12 (DEC-12-AJAA)

 23_8 rd block of the actual binary (starting block in index + 23_8)

 WORD
 FROM
 TO

 353
 6777
 6177

 24_8 th block of the actual binary (starting block in index + 24_8)

 WORD
 FROM
 TO

 161
 7000
 6000

NOTE: Notice the above change from header block to starting block number, when displaying the index of a LAP6-DIAL tape.

SOFTWARE PRODUCT	VERSION		
LAP6-DIAL			
COMPONENT	Version		
FOCAL-12			
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE 1 OF 1	
NEW REPLACEMENT ARTICLE	ORIGINA	AL DATE	
NEW REPLACEMENT ARTICLE X			

FOCAL-12

FADC instruction

It is important to remember that FOCAL-12's FADC instruction references the AD-12 channels as if it were numbered decimally.

Therefore, channel 10 = FADC (8), channel 11 = FADC (9), etc.

	TWARE PRODUCT	VERS	SION	
	COMPONENT	Version		
]	FOCAL-12			
SUBPROGRAM	OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE 1 OF 1	
NEW X	REPLACEMENT ARTICLE	ORIGIN	AL DATE	

LAP6-DIAL ASSEMBLER

LINC mode assembling

PROBLEM:

At times, the LAP6-DIAL Assembler appears to incorrectly assemble LINC mode instructions. The following is an example of the most common:

gggg			*2Ø	
øøøi			•	LMODE
øøø2				SEGMNT 3
ggg3	aaaa	1Ø2Ø		LDA I
øøø4	øøø1	62Ø7		В
øøø5	øøø2	62Ø6		STC C
øøø6		•		
øøø7				
øølø				
øø11				
ØØ12				PMODE
ØØ13				*62ØØ
ØØ14	62ØØ	16Ø6		TAD I C
ØØ15	6201	4215		JMS PRINT
ØØ16				
ØØ17				
øø2ø				
ØØ21				
ØØ22	62Ø6	gggg	С,	ø
øø23	62Ø7	64ØØ	В,	ZLIST
øø24	621Ø	gggg		Ø
ØØ25	6211	gggg		Ø
ØØ26	6212	gggg		Ø
øø27				
øø3ø				
ØØ31	6215	gggg	PRINT,	ø
ØØ32				*64ØØ
øø33	64ØØ	Ø3Ø1	ZLIST,	3Ø1
ØØ34	6401	Ø3Ø2		3Ø2
ØØ35	6402	Ø3Ø3		3Ø3
ØØ36	64Ø3	øøøø		ø
ØØ37	64Ø4	gggg		ø
øø4ø	64Ø5	gggg		Ø

	SOFTWARE PRODUCT LAP6-DIAL		SION
	COMPONENT Version LINC		ion
SUBPROGRAM	SUBPROGRAM OR ADDITIONAL INFORMATION		PAGE OF 3
NEW X	REPLACEMENT ARTICLE	ORIGINA	AL DATE

B 62Ø7 C 62Ø6 PRINT 6215 ZLIST 64ØØ

In the previous example, notice that B and C have full 12 bit values associated with them (see the chart on page 3-3 of the LAP6-DIAL Manual, DEC-12-SE2D-D). Line 5 equals 6206 rather than 4206 because when STC, which equals 40008 is OR'ed with C, which equals 6206, the yield will be 6206 rather than the expected 4206.

The problem is caused by the user symbols defined in PMODE, and then referenced in LMODE, retaining their full 12 bit values. Instead of assembling as an STC into relative location 206 of the particular segment, the assembler yields a JMP to 206 of that segment. (The assembler cannot strip a symbol down to 10 bits because in line 4, 12 bits are really necessary).

SOLUTION:

Depending upon the particular program, a good programming practice to follow is to add an &1777 or an !2000 to the instruction in order to turn on or off the necessary bits as shown in the following example:

aaaa			*2Ø	
øøø1				LMODE
øøø2				SEGMNT 3
øøø3	gggg	1Ø2Ø		LDA I
øøø4	øøøı	62Ø7		В
øøø5	øøø2	42Ø6		STC C&1777
øøø6		•		
øøø7				
ØØ1Ø				
ØØ11				
ØØ12				PMODE
ØØ13				*62ØØ
ØØ14	62ØØ	16Ø6		TAD I C
ØØ15	6201	4215		JMS PRINT

SOF	SOFTWARE PRODUCT		VERSION		
I	AP6-DIAL				
	COMPONENT	Vers	Version		
	LINC				
SUBPROGRAM	OR ADDITIONAL INFORMATION	SEQUENCE #		GE OF	
		1	2	3	
NEW X	REPLACEMENT ARTICLE	ORIGINA	ORIGINAL DATE		

ØØ16				
øø17				
øø2ø				
ØØ21				
øø22	62Ø6	gggg	С,	ø
ØØ23	62 Ø 7	6400	В,	ZLIST
ØØ24	621Ø	gggg	-	ø
ØØ25	6211	gggg		ø
ØØ26	6212	gggg		ø
ØØ27				•
øø3ø				
ØØ31	6215	gggg	PRINT,	ø
ØØ32				*6400
ØØ33	64ØØ	Ø3Ø1	ZLIST,	3Ø1
ØØ34	6401	Ø3Ø2		3Ø2
ØØ35	6492	Ø3Ø3		3Ø3
ØØ36	64Ø3	gggg		ø
øø37	64Ø4	øøøø		ø
ØØ4Ø	64Ø5	gggg		ø

NO ERRORS

В	62Ø7
C	6206
PRINT	6215
ZLIST	6400

SOFTWARE PRODUCT		VERS	VERSION	
]	LAP6-DIAL			
	COMPONENT	Vers	ion	
	LINC			
SUBPROGRAM	OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE	
		1	3 3	
NEW	REPLACEMENT ARTICLE	ORIGINA	AL DATE	

-	·	

MILDRED (DEC-12-FZDA)

Patch to allow reference of units Ø - 77

The current version of MILDRED will only reference units \emptyset - 17. To allow referencing of units \emptyset - 77, change the following location:

IN THE SOURCE:

LINE NUMBER	FROM	TO
0/20/7	7760	77ØØ

IN THE BINARY:

Change the following word in the second block of the binary (second block = starting block + 1)

WORD	FROM	TO	
124	776Ø	77ØØ	

1	SOFTWARE PRODUCT VERSION LAP6-DIAL		SION	
	COMPONENT	Vers	Version	
	MILDRED			
SUBPROGRAM C	PROGRAM OR ADDITIONAL INFORMATION SEQUENCE #		PAG OF	
		1	1	1
NEW X	REPLACEMENT ARTICLE	ORIGINA	AL DATE	

MILDRED (DEC-12-FZAD)

Reassembling MILDRED in odd numbered segments

As currently implemented, MILDRED cannot be reassembled in an odd numbered segment (i.e., segment 1, 5 or 7). To correct this problem change the following locations:

In the Source:

LINE NUMBER	FROM	TO
Ø177	PPNT1	PPNT1&777
Ø2ØØ	STC PPNT2	STC PPNT2&777

If you are reassembling MILDRED, remember to add in a segment X (X- \emptyset to 7) pseudo-op, followed by a *2 \emptyset in the beginning of the source.

SOFTWARE PRODUCT LAP6-DIAL	VERS	SION	
COMPONENT MILDRED	Vers	Version	
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE 1 OF 1	
NEW REPLACEMENT ARTICLE X	ENT ARTICLE ORIGINAL DATE		

MILDRED

Patch to allow MILDRED to address a 1699_8 block LINCtape

To allow MILDRED to create index entries on a 1600_8 block LINCtape, make the following changes to the source and reassemble to generate a new binary.

MILDRED (source) DEC-12-FZDA

LINE NUMBER	FROM	TO
Ø545	-1øøø	-1577
1ø33	7øøø	6 000

SOFTWARE PRODUCT LAP6-DIAL	VERS	SION
COMPONENT MILDRED	Vers	ion
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE #	PAGE 1 OF 1
NEW REPLACEMENT ARTICLE	ORIGINA	AL DATE

LAP6-DIAL PIP

Patch to allow PIP to save programs on a 1600 block LINCtape

To allow PIP (on LINCtape DEC-12-SE2E-UO) save files on a 1699_8 block LINCtape, make the following changes to the binary:

lst block of the actual binary (starting block in
index + 1)

WORD	FROM	TO
113	Ø777	1577

7th block of the actual binary (starting block in index + 7)

WORD	FROM	TO	
356	Ø777	1577	

Note: With this change the "U" option in auxiliary mode will still copy only the first 1000_8 blocks.

The following patch may be used on the PIP source (on LINCtape DEC-12-SEZB-UO, part 1)

PIP Source

LINE NUMBER	FROM	TO
0/237	TUPPER=777	TUPPER=1577

Note: With this source change, once PIP is reassembled and saved, the "U" option will copy a full 1600_8 blocks.

NOTE! Please notice the above change from header block to starting block number, when displaying the index of a LAP6-DIAL tape.

1	SOFTWARE PRODUCT LAP6-DIAL		VERS	SION		
	COMPONENT		Version			
	PIP					
SUBPROGRAM	SUBPROGRAM OR ADDITIONAL INFORMATION		SEQUENCE #	,	PAGE OF	1
			1	1		1
NEW	REPLACEMENT ARTICLE		ORIGINA	AL DA	ſΕ	

LAP6-DIAL PIP

Patch to allow PIP's "D" option to copy a 1600 block LINCtape

To allow PIP (on LINCtape DEC-12-SE2E-UO) to copy a 1600 block tape using the "D" option make the following changes to the binary:

 14_8 th block of the actual binary (starting block in index $+14_8$)

WORD	FROM	TO
221	7332	1113
222	7Ø1Ø	7001

The following patch may be used on the PIP (4) source (on LINCtape DEC-12-SEZB-UO, part 1).

LINE NUMBER	FROM	TO
1264	CLA CLL CML RTR	TAD EUPPER
1265	RAR	IAC

NOTE: This patch assumes the LAP6-DIAL PIP 1 patch has also been implemented.

SOFTWARE PRODUCT LAP6-DIAL	VERSION
COMPONENT	Version
PIP	
SUBPROGRAM OR ADDITIONAL INFORMATION	SEQUENCE # PAGE OF
	2 1 1
NEW REPLACEMENT ARTICLE	ORIGINAL DATE

LAB-8/E SOFTWARE SYSTEM USER'S MANUAL (DEC-8E-ALUMA-A-D)

Conversion of Data to F4 Output Format in the Data Conversion Program MS

When the program "DATA CONVERSION PROGRAM MS" DEC-8E-ACVTA, or DEC-8E-ALMSA-A-UB is used to convert data to F4 (OS/8 FORTRAN 4) output format, the user should be aware of the following:

- The data is written in binary, floating point format,
 85 words per block.
- 2. The last word of each block is random data.
- 3. The data can be read via "Direct Access" under OS/8 FORTRAN.

The last word to each block can be zeroed according to the following patch:

CONTENTS		
5355	JMP	PATCH
3Ø34	DCA	WRITNO
376Ø	DCA I	ENDBUF
5225	JMP	FIL1
6177	ENDBUF,	BUFOUT + 377
	5355 3Ø34 376Ø 5225	5355 JMP 3Ø34 DCA 376Ø DCA I 5225 JMP

This will allow OS/8 FORTRAN to read the data via an unformatted read.

MANUAL NAME	SEQU	ENCE N	10.
LAB-8/E Software System User's Manual		L	
DEC ORDER NO.	PAGE	0)F
(DEC-8E-ALUMA-A-D)		1	1

MASH USER'S MANUAL

Additional notes on Automatic Mode

The following information on the automatic mode should be inserted in the MASH User's Manual (DEC-12-SQ2A-D), as the third paragraph on page 16.

If G is typed again, automatic mode initiates a series of scans that last until the chromatograph run is complete. Pressing one of the right switches on the console terminates scanning and returns the program to the TIC vs. Time plot.

MANUAL NAME	SEQUENCE NO.
MASH User's Manual	1
DEC ORDER NO.	PAGE OF
(DEC-12-SQ2A-D)	1 1

,		

AIPOS USER'S MANUAL (DEC-12-SQ1A)

Documentation correction

PROBLEM:

Page 4-1, Section 4.3 of the AIPOS User's Manual (DEC-12-SQ1A-D) states that the L R command to FOCAL-12 will cause a return to JDB Control. This is an error.

SOLUTION:

The R must be followed by a coma (,). Therefore, the format should be:

L R,

MANUAL NAME	SEQUENCE NO.	
AIPOS User's Manual	1	
DEC ORDER NO.	PAGE OF	
(DEC-12-SQ1A-D)	1 1	

		•	

LAP6-DIAL-MS User's Manual

Correction for Add Binary command

There is an error in the LAP6-DIAL-MS User's Manual as to the actual relocation factor for the binary. The formula on page 4-6 should read:

[(FIELD * 10000 + ADDRESS) - (ORG & 17400)]

The following are a few examples of how this command works:

Lowest origin in program	Specified Address	Relocated <u>To</u>	
* 25Ø	5øø	75ø	
* 5øø	5ØØ	6 00	
* 12ØØ	4000	4200	
* 63ØØ	4000	4300	

MANUAL NAME	SEQUENCE NO.		
LAP6-DIAL-MS User's Manual	1		
DEC ORDER NO.	PAGE	(OF
		1	1