



AlphaServer GS80/160/320

V7.2 Firmware Release Notes and Update Procedures

JUNE 2006

Hewlett-Packard Company
Palo Alto, California



18th Printing, MAY 2006

Copyright © 2006 Hewlett-Packard Company

HP shall not be liable for technical or editorial errors or omissions contained herein, nor for incidental or consequential damages resulting from furnishing, performance, or use of this material. This is provided "as is" and HP disclaims any warranties, express, implied or statutory and expressly disclaims the implied warranties or merchantability, fitness for particular purpose, good title and against infringement.

COMPAQ, the Compaq logo, DEC, the DEC logo, DECPC, ALPHAbook, AlphaPC, AlphaStation, AlphaServer, and VMS Registered in the U.S. Patent and Trademark Office. OpenVMS, Tru64 are trademarks of Compaq Information Technologies Group, L.P. in the United States and/or other countries. UNIX is a trademark of The Open Group in the United States and/or other countries. All other product names mentioned herein may be trademarks or registered trademarks of their respective companies. Compaq Computer Corporation is a wholly-owned subsidiary of the Hewlett-Packard Company. The information in this publication is subject to change without notice.

Table of Contents

1 Introduction	1-1
1.1 Firmware and Operating System Revision Matrix	1-1
1.2 Associated Documentation.....	1-1
2 AlphaServer GS80/160/320 Firmware Release Notes.....	2-1
2.1 Firmware Revision Information	2-1
2.1.1 SRM Console and CSB Micro Firmware Revisions	2-1
2.1.2 PCI I/O Adapter Firmware Revisions	2-1
2.2 Firmware Enhancements and New Features	2-2
2.2.1 SRM Console Enhancements and New Features	2-2
2.2.1.1 SRM Console Enhancements and New Features - from SRM V6.9-1 to V7.2-1	2-2
2.2.2 SCM Monitor Enhancements and New Features	2-3
2.2.2.1 SCM Monitor Enhancements and New Features	2-3
2.2.3 PSM Enhancements and New Features	2-3
2.2.3.1 PSM Enhancements and New Features.....	2-3
2.2.4 HPM Enhancements and New Features	2-3
2.2.4.1 HPM Enhancements and New Features	2-3
2.2.5 PBM Enhancements and New Features	2-3
2.2.5.1 PBM Enhancements and New Features	2-3
2.2.6 XSRM Enhancements and New Features.....	2-3
2.2.6.1 XSRM Enhancements and New Features	2-3
2.3 IMPORTANT!!! Firmware Workarounds and Restrictions.....	2-3
2.3.1 SRM Console Workarounds and Restrictions	2-3
2.3.2 KVM Console Switch Limitation.....	2-2
2.3.3 Setting the System Serial Number.....	2-5
2.3.4 Programming I ² C EEPROM FRU Information on Non-Compaq Memory DIMMs.....	2-5
2.3.5 Running SMOR Utility on KZPCC PCI RAID Adapter via Serial Line.....	2-9
2.3.6 Procedure for Servicing a Non-Master PCI Drawer in an OpenVMS Galaxy Partition	2-10
2.3.7 Suggested UART Communications Settings.....	2-11
2.3.8 SCM Monitor Workarounds and Restrictions.....	2-13
2.3.8.1 Enabling Redundant PCI Drawer Power Supplies	2-14
2.3.9 Restriction on Hot-Swap/Hot-Add.....	2-15
2.3.10 SROM/XSRM Workarounds and Restrictions.....	2-15
2.3.11 Fibre Channel Behavior	2-15
2.3.11.1 Console Messages When Fibre Channel Driver Starts	2-15
2.3.11.2 Messages – MBX Not Ready.....	2-1
2.3.11.3 Command wwidmgr –quickset –item <n>	2-1
3 AlphaServer GS80/160/320 Firmware Update Procedures	3-1
3.1 Updating SRM Console Firmware Using the CD	3-1

3.2 Checking CSB Micro Firmware Revisions	3-4
3.3 Updating CSB Micro Firmware Using the CD	3-7
3.4 Updating PCI I/O Adapter Firmware Using the CD	3-10
3.5 Procedure for Recovering from a Failed LFU Update	3-13
3.5.1 Hardware Connections	3-13
3.5.2 PC/Laptop Operating System Preparation	3-14
3.5.3 Terminal Emulator Settings.....	3-16
3.5.3.1 Opening Previously Created Sessions.....	3-18
3.5.3.2 Changing Baud Rates.....	3-18
3.5.4 Using the SCM Update Command.....	3-18

Table of Tables

Table 1	AlphaServer GS80/160/320 FW/OS Revision Matrix	1-1
Table 2	Associated Documentation	1-1
Table 3	Firmware V7.2 Components and Revisions	2-1
Table 4	PCI I/O Adapter Firmware Revisions	2-2
Table 5	Default UART Variable Settings	2-12



1 Introduction

This guide is intended for users of the **hp** and COMPAQ AlphaServer GS80, GS160, and GS320 Systems.

It provides release notes pertaining to the current release of firmware residing on the system, and describes how to update the various pieces of firmware, if necessary, using the firmware update utility.

1.1 Firmware and Operating System Revision Matrix

The following table shows the revision of the SRM console and CSB components of this firmware release, together with the versions of the operating systems that are supported by this firmware release. Any future version of the operating systems may require a later revision of system firmware in order that all features of the operating system can be supported.

Table 1 AlphaServer GS80/160/320 FW/OS Revision Matrix

SRM Console FW	CSB Micro FW	OpenVMS	Tru64 UNIX
V7.2-1	V6.6(01.22/01:02)	V7.2-2, V7.3-1, V7.3-2	V4.0G, V5.1A, V5.1B

1.2 Associated Documentation

You can find additional information about installing, configuring and booting your AlphaServer GS80/160/320 in the associated documentation listed in the following table:

Table 2 Associated Documentation

Title	Part Number
AlphaServer GS80/160/320 User's Guide	EK-GS320-UG
AlphaServer GS80/160/320 Firmware Reference Manual	EK-GS320-RM
AlphaServer GS160/320 Installation Guide	EK-GS320-IN
AlphaServer GS80 Installation Guide	EK-GSR80-IN



2 AlphaServer GS80/160/320 Firmware Release Notes

2.1 Firmware Revision Information

2.1.1 SRM Console and CSB Micro Firmware Revisions

The Firmware Update Bootfile,"GS320_V7_2.EXE", contains the latest shipping revisions of the firmware. In this release, the firmware revisions of the CSB Microprocessors have not changed. The SRM Console has changed to V7.2-1

The firmware package has the following components (* = changed since the last release):

Table 3 Firmware Components and Revisions

Component	Location of Flash ROM Where Firmware Resides	Firmware Revision
SRM Console	SRM Flash (on STDIO)	V7.2-1 *
VMS PALcode	SRM Flash (on STDIO)	V1.98-2
UNIX PALcode	SRM Flash (on STDIO)	V1.92-1
ISP10x0 FW	SRM Flash (on STDIO)	V5.57
XSROM	PSM Flash	V6.6 (01.26/00:24)
SCM Micro FW	SCM Flash (on STDIO)	V6.6 (01.22/01:02)
PSM Micro FW	PSM Flash	V6.6 (01.22/01:01)
PBM Micro FW	PBM Flash	V6.6 (01.22/01:02)
HPM Micro FW	HPM Flash	V6.6 (01.22/01:02)

2.1.2 PCI I/O Adapter Firmware Revisions

The Firmware Update Bootfile,"GS320_V7_2.EXE", also contains the following revisions of firmware for updating flash ROM on the various PCI I/O Adapters (* = changed since the last release):

Table 4 PCI I/O Adapter Firmware Revisions

Adapter	HW Variant	Firmware Revision
CIPCA	All variants	4.20
DEFPA	All variants	3.20
FCA-2354	All variants	CS3.93A0
FCA-2384	All variants	HS1.91X6
FCA-2684	All Variants	TS1.91X6
KGPSA ¹	-BC	SS3.20X7
KGPSA	-CA	DS3.93A0
KZPCC	All variants	Adapter FW: CQ17 SMOR Utility: 1.12
KZPDC	All variants	3.40
KZPSA ¹	All variants	A12

¹ NOTE: Although the update program contains firmware images for KGPSA-BC and KZPSA, those adapters ARE NOT officially supported on GS80/160/320 Systems. Also note that CCMAB (Memory Channel) IS supported, but firmware update support is not currently provided or needed.

2.2 Firmware Enhancements and New Features

2.2.1 SRM Console Enhancements and New Features

2.2.1.1 SRM Console Enhancements and New Features - from V7.1-2 to V7.2-1

- I/O Option Firmware changes
 - DS-KGPSA-CA (LP8000) - Firmware Revision 3.93A0
 - DS-KGPSA-DA (LP9002) - Firmware Revision 3.93A0
 - DS-KGPSA-EA (LP9802) - Firmware Revision 1.91X6
 - DS-A5132-AA (LP10000) - Firmware Revision 1.91X6
- New module naming for the following I/O devices:
 - DE602-FA => DE602-F*
 - DEGXA-SB/TB => DEGXA-S*/T*
- WWIDMGR code change: do not attempt to get a UDID on a Fibre Channel SAN for SCSI sequential access or SCSI media changer type devices (i.e. tape drives, robot arm)



2.2.2 SCM Monitor Enhancements and New Features

NOTE: There have been some reported cases where the CSB firmware has failed to update. In particular, the HPM. After performing the MICRO update

make certain the version and date code of the individual sections are all the same. If a subsequent firmware update fails it might be required to do a

complete power cycle. (ie. Cycling the power circuit breakers.)

2.2.2.1 SCM Monitor Enhancements and New Features

- No changes for this release.

2.2.3 PSM Enhancements and New Features

2.2.3.1 PSM Enhancements and New Features

- No changes for this release.

2.2.4 HPM Enhancements and New Features

2.2.4.1 HPM Enhancements and New Features

- No changes for this release.

2.2.5 PBM Enhancements and New Features

2.2.5.1 PBM Enhancements and New Features

- No changes for this release.

2.2.5.2 XSROM Enhancements and New Features

- No changes for this release.

2.3 IMPORTANT!!! Firmware Workarounds and Restrictions

This section lists any workarounds or restrictions in system firmware, which may differ from product documentation.

2.3.1 SRM Console Workarounds and Restrictions

- If the system is being used with OpenVMS 7.3-1, and if GALAXY logical partitions are being used, CPU migration functionality cannot be utilized with V6.3 firmware on a CPU that is halted in console mode using the {stop/cpu x followed by set cpu x/migrate=y} OpenVMS command

sequence until the OpenVMS Remedial Kit VMS731_SYS-V0100 (or later) has been installed. CPU migration functionality can be utilized with V6.3 firmware on an active CPU using the {stop/cpu/migrate=y x} OpenVMS command sequence prior to the Remedial Kit installation. Full CPU migration functionality is restored after installation of the Remedial Kit.

- An issue has been discovered with memory DIMMs on GS family systems. The SRM console command *build -dimm* will **not** work correctly on any DIMMs manufactured by Samsung. The command will appear to complete successfully and the proper data will be displayed in the *show fru* command. However, if the AC power is cycled and the system is powered on again a subsequent *show fru* command will show that the data is incorrect for the Samsung DIMMs. It has been determined that the DIMM manufacturer is write-protecting a portion of the EEPROM used to store the DIMM fru data thus making it impossible for the *build -dimm* command to work properly. It is not yet known if this problem will be solved in the future.
- On hard partitioned systems, to properly power off or reset an individual partition, the user **must** execute the **power off** or **reset** from the SRM console (or appropriate operating system application) associated with that partition, not from the SCM monitor. (This is also the preferred mechanism for power off or reset on non-partitioned systems, too). This is required so that the SRM console can quiesce the QBBs and their global ports within that partition before it issues the power off command to the SCM through shared RAM. Although it is possible to power down and reset partitions from the SCM, that partition may not power up properly and unpredictable behavior of the rest of the system may result. This is similar to the requirement of initiating power on and off of individual CPUs from the SRM console or operating system.
- The SRM console internal heap has been increased from 1MB to 2MB in order to accommodate larger configurations. It is recommended to set the SRM console environment variable, "heap_expand", back to zero and then re-initialize the console. On certain extremely large configurations 2MB may still not be adequate. In these cases the SRM console will automatically detect the resource deficiency and automatically further increase the heap by setting "heap_expand", appropriately and then re-initialize itself.
- After updating the SRM console, if the console performs re-sizing of the heap, you may see the following message, "Bootstrap address collision, image loading aborted", during a boot of Tru64 UNIX. This generally indicates that it is necessary to boot the generic kernel and re-gen a new custom kernel in order to adjust to the new console mapping.
- There is a Blitz TD2921, "GS80/160/320 SRM INIT Heap Expand Loop Explanation". This blitz describes how configurations with many KGPSA adapters and many disks can require heap to be expanded while using WWIDMGR commands. Please note that the "heap_expand" environmental variable can be reset to its former setting for normal operation when WWIDMGR commands are not required.

2.3.2 KVM Console Switch Limitations

2.3.2.1 Run Bios Command in Graphics Mode Not Supported

Use of the SRM "run bios" command from the graphics console when connected through the KVM is not supported, and will result in unexpected keyboard behavior. As a workaround, use the SRM "run bios" command from the serial console via a serial port connection.

2.3.3 Setting the System Serial Number

In order to write the system serial number the system must be powered off, de-partitioned and powered back on. Once at the console prompt the `set sys_serial_num` command can be issued then followed by the serial number. The console will then instruct the SCM (via shared RAM) to propagate the serial number to every FRU in the system that contains an I²C EEPROM. Progress messages indicating which nodes are being programmed will be displayed to the console.

example:

```
P00>>>set sys_serial_num ni12345678

~I~ Updating Sys_serial_num for FRUs present on CSB node:40 ...
~I~ Updating Sys_serial_num for FRUs present on CSB node:30 ...
~I~ Updating Sys_serial_num for FRUs present on CSB node:10 ...
~I~ Updating Sys_serial_num for FRUs present on CSB node:10 ...
~I~ Updating Sys_serial_num for FRUs present on CSB node:31 ...
~I~ Updating Sys_serial_num for FRUs present on CSB node:32 ...
~I~ Updating Sys_serial_num for FRUs present on CSB node:33 ...
~I~ Updating Sys_serial_num for FRUs present on CSB node:11 ...
~I~ Updating Sys_serial_num for FRUs present on CSB node:11 ...
P00>>>
P00>>>show sys_serial_num
sys_serial_num          ni12345678
P00>>>
```

Note: the system serial can only be set and displayed from the SRM console. If a new FRU is later installed an error will be displayed in the `show fru` output until the `set sys_serial_num` is issued again.

Note: the `set sys_serial_num` command can take up to 1 minute to complete. After issuing the command, please wait for 1 minute before proceeding.

2.3.4 Programming I²C EEPROM FRU Information on Non-Compaq Memory DIMMs

The SRM console command `build -dimm` is used to write Compaq style part and serial numbers into DIMMs that are not manufactured by Compaq. The manufacturer's part and serial numbers will still be displayed in the appropriate columns of the `show fru` command but the new Compaq part and serial numbers will also be displayed in the Model/Other and Alias/Misc fields respectively.

For the current implementation of the `build -dimm` command there are a couple of restrictions that must be kept in mind.

1. The `set sys_serial_num` command **must** be executed before the DIMMs can be programmed.
2. The SCM's non-volatile variable `dimm_read_dis` must be set to a 0. This must be done prior to poweron.
3. The DIMM FRU data can only be programmed once. Once the data is written the Compaq JEDEC ID is programmed into the DIMM and will cause the writing of the data to be bypassed on subsequent attempts.



- 4. There is no progress information displayed by the SRM Console as the procedure is executing. Currently the user **must** wait three minutes per QBB (or 5.6 seconds per DIMM) for the procedure to complete.

In future firmware releases there are plans to remove restrictions 3 and 4. The following is an example of a *build -dimm* executed on a 16P system:

```
P00>>>build -dimm
This operation can take as long as 3 minutes per QBB.
Please do not disturb this system during this time.
Since this operation is done in the background on the CSB
no completion notification will take place.
P00>>>
P00>>>
P00>>>
Local escape sequence verified

SCM_E0>
SCM_E0>
SCM_E0> sh fru
FRUname      E Part#      Serial#  Model/Other Alias/Misc
PBP0         00 54-25027-01.E01  NI92960262 WF08LTA111 WFFW_LAB_PSM_DEV
PBP0.SIO     00 B4190-BA.B02    NI92660342 WF08LTA111 WFFW_LAB_PSM_DEV
PBP0.RIO0    00 B4171-AA.E02    NI93871237
PBP0.RIO1    00 B4171-AA.E02    NI93871402
PBP1         00 54-25027-01.E02  NI93670860 WF08LTA111 WFFW_LAB_PSM_DEV
PBP1.SIO     00 B4190-BA.B02    NI93371331 WF08LTA111 WFFW_LAB_PSM_DEV
PBP1.RIO0    00 B4171-AA.E02    NI94270090
PBP1.RIO1    00 B4171-AA.E02    NI94270267
QBB0         00 54-25045-01.A01  NI93900000 WF08LTA111 WFFW_LAB_PSM_DEV
QBB0.PSM     00 54-25074-01.H02  NI93971076
QBB0.PWR     00 54-25017-01.E03  NI93060261 WF08LTA111 WFFW_LAB_PSM_DEV
QBB0.AUX     00 54-25123-01.E01  NI94171119 WF06LTA114 WFFW_LAB_32P_DEV
QBB0.CPU0    04 B4125-AA.E02    NI94170333 .....
QBB0.CPU1    00 B4125-AA.E02    NI94170122 .....
QBB0.CPU2    00 B4125-AA.E02    NI94170347 .....
QBB0.CPU3    00 B4125-AA.E02    NI94170393 .....
QBB0.MEM0    00 B4150-AA.D04    SM01900932
QBB0.MEM0.DIM0 00 ..... ??000  01CSA-08  ni123456780000
QBB0.MEM0.DIM1 00 ..... ??000  01CSA-08  ni123456780010
QBB0.MEM0.DIM2 00 ..... ??000  01CSA-08  ni123456780020
QBB0.MEM0.DIM3 00 ..... ??000  01CSA-08  ni123456780030
QBB0.DIR     00 73-B4140-AA.D01  NI94670442 WF06LTA114 WFFW_LAB_32P_DEV
QBB0.DIR0.DIM0 00 54-25023-DA.A01  SW07000301 .....
QBB0.DIR0.DIM1 00 54-25023-DA.A01  SW07000212 .....
QBB0.DIR0.DIM2 00 54-25023-DA.A01  SW07000152 .....
QBB0.DIR0.DIM3 00 54-25023-DA.A01  SW07000217 .....
QBB0.DIR0.DIM4 00 54-25023-DA.A01  SW07000122 .....
QBB0.DIR0.DIM5 00 54-25023-DA.A01  SW07000279 .....
QBB0.DIR0.DIM6 00 54-25023-DA.A01  SW07000302 .....
QBB0.DIR0.DIM7 00 54-25023-DA.A01  SW07000312 .....
```



QBB0.IO01 00 -B4170-AA.E01 NI94173724 WF08LTA111 WFFW_LAB_PSM_DEV
QBB0.GP 00 B4180-BA.A03 NI94270815 WF08LTA111 WFFW_LAB_PSM_DEV
QBB1 00 54-25045-01.A01 NI93900000 WF08LTA111 WFFW_LAB_PSM_DEV
QBB1.PSM 00 54-25074-01.H02 NI93971109
QBB1.PWR 00 54-25017-01.E02 NI93060412
QBB1.AUX 00 54-25123-01.E01 NI93970629 WF06LTA114 WFFW_LAB_32P_DEV
QBB1.CPU0 00 B4125-AA.E02 NI94371010
QBB1.CPU1 00 B4125-AA.E02 NI94370702
QBB1.CPU2 00 B4125-AA.E02 NI94270689
QBB1.CPU3 00 B4125-AA.E02 NI94370906
QBB1.MEM1 00 B4150-AA.D04 SM01901161
QBB1.MEM1.DIM0 00 54-24941-JA.C03 AY93300804 00DSA-08 ni123456781100
QBB1.MEM1.DIM1 00 54-24941-JA.C03 AY93300801 00DSA-08 ni123456781110
QBB1.MEM1.DIM2 00 54-24941-JA.C03 AY93301133 00DSA-08 ni123456781120
QBB1.MEM1.DIM3 00 54-24941-JA.C03 AY93300806 00DSA-08 ni123456781130
QBB1.MEM1.DIM4 00 54-24941-JA.C03 AY93300739 00DSA-08 ni123456781140
QBB1.MEM1.DIM5 00 54-24941-JA.C03 AY93422807 00DSA-08 ni123456781150
QBB1.MEM1.DIM6 00 54-24941-JA.C03 AY93300807 00DSA-08 ni123456781160
QBB1.MEM1.DIM7 00 54-24941-JA.C03 AY93422977 00DSA-08 ni123456781170
QBB1.MEM2 00 B4150-AA.D01 NI91960469 MEMORY SHMOO
QBB1.MEM2.DIM0 00 54-24941-JA.C03 AY93422809 00DSA-08 ni123456781200
QBB1.MEM2.DIM1 00 54-24941-JA.C03 AY93422811 00DSA-08 ni123456781210
QBB1.MEM2.DIM2 00 54-24941-JA.C03 AY93422881 00DSA-08 ni123456781220
QBB1.MEM2.DIM3 00 54-24941-JA.C03 AY93300844 00DSA-08 ni123456781230
QBB1.MEM2.DIM4 00 54-24941-JA.C03 AY93422883 00DSA-08 ni123456781240
QBB1.MEM2.DIM5 00 54-24941-JA.C03 AY93300833 00DSA-08 ni123456781250
QBB1.MEM2.DIM6 00 54-24941-JA.C03 AY93300710 00DSA-08 ni123456781260
QBB1.MEM2.DIM7 00 54-24941-JA.C03 AY93300732 00DSA-08 ni123456781270
QBB1.MEM3 00 B4150-AA.D01 NI91960374 MEMORY SHMOO
QBB1.MEM3.DIM0 00 54-24941-JA.C03 AY93300831 00DSA-08 ni123456781300
QBB1.MEM3.DIM1 00 54-24941-JA.C03 AY93301179 00DSA-08 ni123456781310
QBB1.MEM3.DIM2 00 54-24941-JA.C03 AY93422922 00DSA-08 ni123456781320
QBB1.MEM3.DIM3 00 54-24941-JA.C03 AY94700458 00DSA-08 ni123456781330
QBB1.MEM3.DIM4 00 54-24941-JA.C03 AY92605652 00DSA-08 ni123456781340
QBB1.MEM3.DIM5 00 54-24941-JA.C03 AY94700488 00DSA-08 ni123456781350
QBB1.MEM3.DIM6 00 54-24941-JA.C03 AY94600158 00DSA-08 ni123456781360
QBB1.MEM3.DIM7 00 54-24941-JA.C03 AY94600150 00DSA-08 ni123456781370
QBB1.DIR 00 -B4140-AA.D01 NI94471054
QBB1.DIR0.DIM0 00 54-25023-BA.A01 NI92961673
QBB1.DIR0.DIM1 00 54-25023-BA.A01 NI93260267
QBB1.DIR0.DIM2 00 54-25023-BA.A01 NI94160044
QBB1.DIR0.DIM3 00 54-25023-BA.A01 NI94160015
QBB1.DIR0.DIM4 00 54-25023-BA.A01 NI94061174
QBB1.DIR0.DIM5 00 54-25023-BA.A01 NI92961681
QBB1.DIR0.DIM6 00 54-25023-BA.A01 NI94060105
QBB1.DIR0.DIM7 00 54-25023-BA.A01 NI93260068
QBB1.GP 00 -B4181-BA.A02 NI93470534 WF08LTA111 WFFW_LAB_PSM_DEV
QBB2 00 54-25043-01.D03 NI94470374 WF08LTA111 WFFW_LAB_PSM_DEV
QBB2.PSM 00 54-25074-01.K01 NI91860245
QBB2.PWR 00 54-25017-01.F01 NI94171185
QBB2.AUX 00 54-25123-01.E01 NI94170906
QBB2.CPU0 00 B4125-AA.E02 NI94370093



QBB2.CPU1 00 B4125-AA.E02 NI94170187
QBB2.CPU2 00 B4125-AA.E02 NI94170300
QBB2.CPU3 00 6X-B4125-AA.B02 NI93260204
QBB2.MEM0 00 B4150-AA.D01 NI92460122 WF08LTA111 WFFW_LAB_PSM_DEV
QBB2.MEM0.DIM0 00 54-24941-FA.C03 AY92604508 00DSA-08 ni123456782000
QBB2.MEM0.DIM1 00 54-24941-FA.C03 AY92604543 00DSA-08 ni123456782010
QBB2.MEM0.DIM2 00 54-24941-FA.C03 AY92604507 00DSA-08 ni123456782020
QBB2.MEM0.DIM3 00 54-24941-FA.C03 AY92604544 00DSA-08 ni123456782020
QBB2.MEM0.DIM4 00 54-24941-FA.C03 AY92604542 00DSA-08 ni123456782020
QBB2.MEM0.DIM5 00 54-24941-FA.C03 AY92604447 00DSA-08 ni123456782050
QBB2.MEM0.DIM6 00 54-24941-FA.C03 AY92604443 00DSA-08 ni123456782060
QBB2.MEM0.DIM7 00 54-24941-FA.C03 AY9260444 00DSA-08 ni123456782070
QBB2.MEM1 00 -B4150-AA.D02 NI94070657
QBB2.MEM1.DIM0 00 54-24941-FA.C03 AY92604621 01CSA-08 ni123456782100
QBB2.MEM1.DIM1 00 54-24941-FA.C03 AY92604652 01CSA-08 ni123456782110
QBB2.MEM1.DIM2 00 54-24941-FA.C03 AY92604622 01CSA-08 ni123456782120
QBB2.MEM1.DIM3 00 54-24941-FA.C03 AY92604635 01CSA-08 ni123456782130
QBB2.MEM1.DIM4 00 54-24941-FA.C03 AY92604677 01CSA-08 ni123456782140
QBB2.MEM1.DIM5 00 54-24941-FA.C03 AY92604619 01CSA-08 ni123456782150
QBB2.MEM1.DIM6 00 54-24941-FA.C03 AY92604618 01CSA-08 ni123456782160
QBB2.MEM1.DIM7 00 54-24941-FA.C03 AY92604654 01CSA-08 ni123456782170
QBB2.MEM2 00 B4150-AA.D02 NI94070620
QBB2.MEM2.DIM0 00 54-24941-JA.C03 AY91895031 00DSA-08 ni123456782200
QBB2.MEM2.DIM1 00 54-24941-JA.C03 AY94600198 00DSA-08 ni123456782210
QBB2.MEM2.DIM2 00 54-24941-JA.C03 AY94700506 00DSA-08 ni123456782220
QBB2.MEM2.DIM3 00 54-24941-JA.C03 AY94700512 00DSA-08 ni123456782230
QBB2.MEM2.DIM4 00 54-24941-JA.C03 AY94700532 00DSA-08 ni123456782240
QBB2.MEM2.DIM5 00 54-24941-JA.C03 AY94301291 00DSA-08 ni123456782250
QBB2.MEM2.DIM6 00 54-24941-JA.C03 AY94700528 00DSA-08 ni123456782260
QBB2.MEM2.DIM7 00 54-24941-JA.C03 AY92605707 00DSA-08 ni123456782270
QBB2.MEM3 00 -B4150-AA.D04 NI94471226
QBB2.MEM3.DIM0 00 54-24941-FA.C03 AY92625463 00DSA-08 ni123456782300
QBB2.MEM3.DIM1 00 54-24941-FA.C03 AY92626141 00DSA-08 ni123456782310
QBB2.MEM3.DIM2 00 54-24941-FA.C03 AY92617338 00DSA-08 ni123456782320
QBB2.MEM3.DIM4 00 54-24941-FA.C03 AY92617336 00DSA-08 ni123456782340
QBB2.MEM3.DIM5 00 54-24941-FA.C03 AY92626175 00DSA-08 ni123456782350
QBB2.MEM3.DIM6 00 54-24941-FA.C03 AY92716902 00DSA-08 ni123456782360
QBB2.MEM3.DIM7 00 54-24941-FA.C03 AY92617390 00DSA-08 ni123456782370
QBB2.DIR 00 -B4140-AA.D01 NI94670625 WF08LTA111 WFFW_LAB_PSM_DEV
QBB2.DIR0.DIM0 00 54-25023-BA.A01 NI94060311
QBB2.DIR0.DIM1 00 54-25023-BA.A01 NI92961393
QBB2.DIR0.DIM2 00 54-25023-BA.A01 NI92961885
QBB2.DIR0.DIM3 00 54-25023-BA.A01 NI92961639
QBB2.DIR0.DIM4 00 54-25023-BA.A01 NI92961411
QBB2.GP 00 B4180-BA.A02 NI93970472 WF08LTA111 WFFW_LAB_PSM_DEV
QBB3 00 54-25043-02.D03 NI94470479 WF08LTA111 WFFW_LAB_PSM_DEV
QBB3.PSM 00 54-25074-01.K01 NI94770199
QBB3.PWR 00 54-25123-01.E01 NI94170951 WF08LTA111 WFFW_LAB_PSM_DEV
QBB3.AUX 00 54-25123-01.E01 NI94170951 WF08LTA111 WFFW_LAB_PSM_DEV
QBB3.CPU0 00 -B4125-AA.E02 NI94370845
QBB3.CPU1 00 B4125-AA.E02 NI94270669
QBB3.CPU2 00 B4125-AA.E02 NI94170358



```

QBB3.CPU3    00 B4125-AC.A01    SM007000CD
QBB3.DIR     00 -B4140-AA.D01    NI93870621 WF08LTA111 WFFW_LAB_PSM_DEV
QBB3.DIR0.DIM1 00 ..... ??000 .....
QBB3.DIR0.DIM2 00 54-25023-BA.A01 NI92961537 .....
QBB3.IO01    00 -B4170-AA.E01    NI94173767 WF08LTA111 WFFW_LAB_PSM_DEV
QBB3.GP      00 B4181-BA.A03    NI94072674 WF08LTA111 WFFW_LAB_PSM_DEV
HSW4        00 B4340-01.A00    AY12312312
HSW4.HPM0    02 54-25115-01.B04    NI93470032
HSW4.PWR2    00 54-30194-01.D01    NI94271542
SCM_E0>

```

2.3.5 Running SMOR Utility on KZPCC PCI RAID Adapter via Serial Line

The KZPCC PCI RAID Adapter has an embedded BIOS ROM Utility called “SMOR”, which can be used to configure the adapter and update the on-board firmware components. The following example shows how to invoke SMOR from the SRM Console (in serial mode), on a KZPCC named pza0 :

```

<<User types “run bios” command from SRM Console prompt>>
P00>>>run bios pza0

```

<<Screen blanks here, wait a few seconds, then new screen appears>>

Running the graphics console emulation on a serial port.

Press <SPACE> to hold this screen (until you press another key).

The <ESC> key is used to emulate the functionality of the <ALT> key. For example, to deliver the <ALT - H> key combination, press the <ESC> key and then the <H> key.

The <ESC> key is also used to ensure the delivery of <F1>,,<F9> keys in case the VT keyboard function keys are programmed. For example, to deliver the <F3> key, press the <ESC> key and then the <3> key.

To deliver the <ESC> key itself, press the <ESC> key and then the <SPACE> key.

Press <ESC> and <SPACE> to quit the graphics console emulation and exit, Press any other key to continue.

.....

```

<<User types <space> <space> or waits ~15 seconds>>
<<Screen blanks here, wait ~15 seconds, then new screen appears>>

```

```

          I2O SCSI BIOS v001.2H (1999/10/15)
    Distributed Processing Technology
    Copyright 1996-99 All Rights Reserved
Hit <CTRL+D> for DPT Setup, Waiting for devices

```

```

<<User types <CTRL+D> >>
<<Screen blanks here, wait ~15 seconds, then new screen appears>>

```




2. Determine which local IO risers are attached to the PCI drawer and then which IOR numbers are assigned to them by the SRM console. Using the PCI drawer ID (from the thumbwheel switch), look for that PCI box number in the “show config” output and then for the corresponding local IO riser numbers. Using “grep” simplifies this task.
P00>>> show config | grep Side
P00>>> show config | grep IOR
3. Power off the logical local IO risers (one per cable) from the SRM console.
P00>>> power off -ior 8
P00>>> power off -ior 9
4. Re-initialize the SRM console so it can map out the IO that was just removed.
P00>>> init
5. Determine the CSB address of the PCI drawer to be powered off. Note, the CSB address of a PCI drawer is simply 10h plus the PCI drawer ID, 0-Fh, hence a value 10h-1Fh.
P00>>> scm show system
6. From the Master SCM power off the PCI drawer. Important: Currently this needs to be done at the Master SCM.
SCM_E0> power off -csb 12
7. Service the PCI drawer.
At this point the PCI drawer may be serviced.
8. From the Master SCM power on the PCI drawer.
SCM_E0> power on -csb 12
9. From the soft partition’s SRM console, power on the local IO risers for the PCI drawer.
P00>>> power on -ior 8
P00>>> power on -ior 9
10. Re-initialize the SRM console so that it can rediscover the PCI options in the PCI drawer.
P00>>>init
11. Boot the operating system.
P00>>> boot
...
\$

Note, identifying the correct local IOR numbers and PCI box CSB ID are crucial to safely powering down the PCI drawer without affecting the other soft partitions. Care should be taken to correctly determine these parameters.

2.3.7 Suggested UART Communications Settings

Due to some recent confusion regarding UART settings, this subsection is a compilation of information on the subject. It includes information on default settings, suggested methods of usage and some excerpts from previous release notes.

Defaults:

The following are the default settings for all UART-related SCM variables. The variables are set to these values when either the SCM’s EEPROM checksum test fails or a user has installed the RMC_DEFAULTS jumper. The SCM’s *build eeprom* command will not modify the baud rate and the



flow control settings for any of the three UARTs. It will, however, set the COM1 mode back to “through” if it has been modified.

Table 5 Default UART Variable Settings

UART	Baud rate	Flow control	Mode
local	9600	soft	n/a
COM1	9600	hard	through
modem	9600	hard	n/a

Suggestions and preferred settings:

Although local and COM1 baud rates are supported up to 57600 we recommend a setting of 9600. This is because we have experienced serial character loss and corruption due to terminal emulator programs improperly rendering the data which is sent to them from the SCM. With the use of serial analyzers it has been proven that the data which is displayed on the operator console is not always consistent with the data which it was sent by the SCM. We have also noticed that the only way to reliably alleviate this problem is to reduce the baud rate. We have found no other combination of terminal window settings which guarantee data integrity.

Another thing to keep in mind is that although the firmware default for the COM1 flow control setting is “hard”, the default setting for Unix is “soft”. If a user wants Unix to use soft flow control then the /etc/gettydefs file must be edited to keep Unix from changing the setting. This is also true if a user wishes to run the Unix OPA0 console at any speed other than 9600. Unix must first be brought up at 9600, the file modified, the baud rates changed at the console and finally Unix can be restarted and it will use the operator console at the new baud rate.

Using the SMC and graphics programs:

The SMC PC allows the user to connect to each SCM in the system by providing a terminal window to each standard I/O local port via a DS90M terminal server. Typically the SMC is connected such that each port is attached to one hard partition in the system (i.e. port 1 connects to the local port for the first partition, port 2 connects to the second partition, etc). Therefore, in an 8 way hard-partitioned system each terminal server port is connected to one of the hard partition local ports.

When the SMC software installs itself from the CD it will configure the terminal server ports to use software flow control. Some serially-based utilities which attempt to draw graphics-like pictures on the terminal window will turn off flow control from the operating system. One such utility is Unix’s sysman. If such a program is going to be run a couple of configuration changes should be made if any data corruption is seen in the terminal window.

First: In order to insure that graphics characters are not misinterpreted as an XON or an XOFF character the terminal server port’s flow setting must be changed from XON/XOFF to none or disabled. In order to do this the Access Server Manager program must be started. From the Browser window select the terminal server for the system being accessed and click on “open”. This will start an Access Server window. From here you can select the “utilities” tab and after choosing “connect to the telnet console” click on “do it now”. This opens a session to the console port of the terminal server. From this window



you can issue the following commands to turn off a particular port's flow control. From the "local" prompt issue the following commands:

```
Local>set port x input flow disabled
Local>set port x output flow disabled
Local>set port x flow control disabled
```

This should guarantee that the terminal server will neither interpret nor generate an XON or an XOFF for port x. Use the *show port x* command to verify that the desired settings have been selected. To re-enable flow control issue the following commands:

```
Local>set port x input flow enabled
Local>set port x output flow enabled
Local>set port x flow control xon
```

Second: some odd behavior has been seen with using the first port of the DS90M terminal server. On occasion, even though flow control has been turned off, it is possible that certain characters are interpreted by the DS90 instead of simply being passed through. In cases where less than eight local ports are necessary we recommend that using the first port be avoided. With flow control and baud rates properly set for the given application being run, character corruption has been seen very rarely and only when connected through the first port of the terminal server.

2.3.8 SCM Monitor Workarounds and Restrictions

- Before updating CSB Micro Firmware to the latest revisions, all micros and XSROM should be at the same firmware revision (all V5.6 or all V5.7 or all V5.8, etc.) for correct operation.
- In hard partitioned systems to properly power off or reset an individual partition, **do not** use the SCM monitor. Instead, use the SRM console (or appropriate operating system application) associated with that partition to execute the power off or reset.
- If the message "~E~ EEPROM VERSION MISMATCH is encountered, perform the following procedure to update the EEPROM. From the SCM monitor do a 'show nvram' and 'show status' and make note of any custom settings (for example, hard partitioning environment variables, Baud rates, etc.). Then do a 'build eeprom'. When this completes, then restore your custom settings.
- In partitioned systems, not all functions of the CSB master SCM are available on slave SCMs. Consult the system documentation for a list of the supported commands of SCM slaves.
- The SCM parser supports "enable test <number>" and "disable test <number>" commands for SRM and XSROM user mode tests. Note, to return to the system defaults, use the "build eeprom" command or "set srom full" and "set xsrom full".
- In the event of a CPU failure on power-up (such as an XSROM-detected CPU hardware error), the failing CPU is mapped out of the active configuration, but is left in the power-up state. Because the CPU is mapped out of the active configuration, it cannot be powered off by the



operating system for replacement. If the operator wishes to power off the module, they can do so via the SCM command "p off -cpu <CSB_cpu#>", where <CSB_cpu#> is the CPU number as reported by the SCM "show csb" command (for example, "C0" or "D4").

2.3.8.1 Enabling Redundant PCI Drawer Power Supplies

When a power supply is added to a PCI drawer to enable power redundancy the operation may not have the expected results. If the drawer is currently powered on the expected behavior is that the newly introduced supply also be enabled. It has been found that this functionality does not work in any PBM micro image dated between Jan 12, 2000 and Mar 29, 2001. This includes firmware releases V5.6 through the V5.9B.

If a PBM image dated in this range is being used then when the supply is introduced and plugged in it's VAUX LED will be turned on but it will not be enabled. It's power OK LED will not be turned on. There are several ways in which this new supply can be enabled:

1. The system can be powered off and back on via either the CLI or the keyswitch. This will take down the entire system.
2. The drawer can be powered down from the SCM CLI using the *power off -csb 10* command. Where 10 is the CSB address of the PCI drawer as displayed by the SCM command *show csb*. The drawer can then be powered back on and both supplies will be enabled. This may fault the hard partition of which this drawer is a member or even the entire system. To avoid the fault the hard partition containing the drawer could be powered down first.
3. The following commands can be executed from the SCM CLI. First, find the CSB address of the PCI drawer by using the *show csb* command from the SCM. Then execute the two commands below:

```
SCM_EF> show csb

CSB Type          Firmware Revision   FSL Revision   Power State
1F PBM            V05.9(03.14/11:03) V5.6(05.31)   ON
EF SCM MASTER     V05.9(03.14/11:04) V5.6(05.31)   ON

SCM_EF> exam &mlf -ipr d04
CSB_1F/00000D04: 8338
SCM_EF> deposit &mlf -ipr d04 c338
SCM_EF> exam &mlf -ipr d04
CSB_1F/00000D04: C33C
SCM_EF>
```

The two upper bits of the 16 bit IPR represent the power enable signals for the two power supplies. By setting the two bits ("C" in C338) both supplies are turned on. In order to calculate the value to be



written you must “OR in” the upper two bits to the value read. The other 14 bits should be left unchanged (i.e. written back with the values which were read). This sequence of commands will not take down the hard partition of which this drawer is a member.

2.3.9 Restriction on Hot-Swap/Hot-Add

- It is NOT a valid configuration to hot-swap in a “slow” CPU (B4125) into a “fast” QBB (a QBB running at 9X or higher speeds).

2.3.10 SRROM/XSRROM Workarounds and Restrictions

- Before updating CSB Micro Firmware to the latest revisions, all micros and XSRROM should be at the same firmware revision (all V5.6 or all V5.7 or all V5.8, etc.) for correct operation.

2.3.11 Fibre Channel Behavior

2.3.11.1 Console Messages When Fibre Channel Driver Starts

When the console fibre channel driver starts, you may see the message “**pga0.0.0.2.4 – Nvram read failed**”. This message indicates the KGPSA’s NVRAM is either unformatted or is not working properly. The more likely reason is an unformatted NVRAM.

Beginning with V5.6 console firmware:

- The console contains a portion of the NVRAM to indicate if the adapter should be initialized to a Fabric (Switch) topology or initialized to a Loop topology. By default, the console initializes the KGPSA to a Fabric topology.
- The NVRAM is automatically formatted when the topology is set.
- Reference : WWIDMGR USERS MANUAL

http://ftp.digital.com/pub/DEC/Alpha/firmware/v*./doc/wwidmgr.pdf

```
P00>>>wwidmgr -show ada
item  adapter          WWN          Cur. Topo  Next Topo
pga0.0.0.8.1 - Nvram read failed.
[ 0] pga0.0.0.8.1  1000-0000-c920-05ab    FABRIC    UNAVAIL
pgb0.0.0.10.1 - Nvram read failed.
[ 1] pgb0.0.0.10.1 1000-0000-c921-0ce0    FABRIC    UNAVAIL
[9999] All of the above.
LP00>>>wwidmgr -set adapter -item 9999 -topo fabric
pga0.0.0.8.1 - Nvram read failed.
Reformatting nvram
pgb0.0.0.10.1 - Nvram read failed.
```



Reformatting nvram

LP00>>>wwidmgr -show ada

item	adapter	WWN	Cur. Topo	Next Topo
[0]	pga0.0.0.8.1	1000-0000-c920-05ab	FABRIC	FABRIC
[1]	pgb0.0.0.10.1	1000-0000-c921-0ce0	FABRIC	FABRIC

[9999] All of the above.

LP00>>>init



2.3.11.2 Messages – MBX Not Ready

KNOWN PROBLEM:

You may see a "*** MBX not ready ***" error when formatting the Nvram with the "wwidmgr -set ada" command. Reissuing this command should succeed:

```
P00>>>wwidmgr -set ada -item 9999 -topo fab
pga0.0.0.6.1 - Nvram read failed.
Reformatting nvram
*** MBX not ready ***
pgb0.0.0.1.2 - Nvram read failed.
Reformatting nvram
P00>>>wwidmgr -show ada
item adapter WWN Cur. Topo Next Topo
*** MBX not ready ***
pga0.0.0.6.1 - Nvram format incorrect.
[ 0] pga0.0.0.6.1 1000-0000-c920-a763 FABRIC UNAVAIL
[ 1] pgb0.0.0.1.2 1000-0000-c920-c9fe FABRIC FABRIC
[9999] All of the above.
P00>>>wwidmgr -set ada -item 9999 -topo fab
P00>>>wwidmgr -show ada
item adapter WWN Cur. Topo Next Topo
[ 0] pga0.0.0.6.1 1000-0000-c920-a763 FABRIC FABRIC
[ 1] pgb0.0.0.1.2 1000-0000-c920-c9fe FABRIC FABRIC
[9999] All of the above.
```

2.3.11.3 Command *wwidmgr -quickset -item <n>*

KNOWN PROBLEM:

Command "wwidmgr -quickset -item <n>" MUST also have the "-unit" qualifier on the line. This functionality is not working properly, and a -unit MUST be specified.
Reference : WWIDMGR USERS MANUAL
"If no unit number is specified, console will generate one that is a hashed value of the WWID."



3 AlphaServer GS80/160/320 Firmware Update Procedures

This chapter explains how to upgrade the AlphaServer GS80/160/320 firmware using the Loadable Firmware Update Utility (LFU) on the Alpha Systems Firmware Update CD. **In the examples which follow, the firmware revisions of the updates are not necessarily the latest revisions currently available. They are provided as examples only.**

3.1 Updating SRM Console Firmware Using the CD

NOTE: It is recommended that you run the LFU from the serial line with the “console” environment variable set to “serial” mode. In “graphics” mode, after updating CSB Micros, the graphics monitor will go blank, and you will have to do an SCM “p on” command from the serial line, to restart the system.

It is necessary to Power Off, “De-Partition”, and Power On the system, before running the LFU. The LFU program is booted from the SRM Console prompt.

SRM Console Firmware Update Example Using LFU :

1. Load the “Alpha Systems Firmware Update CD Vx.x” into the CD-ROM Drive. Then, from the SRM Console prompt, Initialize the System :

```
P00>>>init

OpenVMS PALcode V1.88-1, Tru64 UNIX PALcode V1.83-1

system = QBB 0 1 2 3          + HS
  QBB 0 = CPU 0 1 2 3 + Mem 0   2 3 + Dir + IOP + PCA 0 1      + GP (Hard QBB 0)
  QBB 1 = CPU 0 1 2 3 + Mem 0   + Dir + IOP + PCA              + GP (Hard QBB 1)
  QBB 2 = CPU 0 1 2 3 + Mem 0 1  + Dir + IOP + PCA              + GP (Hard QBB 2)
  QBB 3 = CPU 0 1 2 3 + Mem 0 1  + Dir + IOP + PCA              2 + GP (Hard QBB 3)
micro firmware version is V5.8
shared RAM version is 1.4
.
.
<SEVERAL PAGES OF PRINTOUT WILL OCCUR HERE>
.
.
AlphaServer Console V5.8-251, built on Nov 17 2000 at 11:03:28
P00>>>
```

2. Enter <show dev> to find name of CD-ROM Drive (dqa0 in this example) :

```
P00>>>sho dev
dka0.0.0.1.0          DKA0          COMPAQ BB00921B91  3B05
dkb0.0.0.1.28        DKB0          COMPAQ BB00921B91  3B05
dkc0.0.0.5.29        DKC0          COMPAQ BB00911CA0  3B05
dkc100.1.0.5.29      DKC100        COMPAQ BB00911CA0  3B05
```



```

dkc200.2.0.5.29          DKC200          COMPAQ BB00911CA0  3B05
dkc300.3.0.5.29          DKC300          COMPAQ BB00911CA0  3B05
dkc400.4.0.5.29          DKC400          COMPAQ BB00911CA0  3B05
dkc500.5.0.5.29          DKC500          COMPAQ BB00911CA0  3B05
dqa0.0.0.15.0            DQA0            COMPAQ CDR-8435    0013
dqb0.0.0.15.28          DQB0            COMPAQ CDR-8435    0013
dva0.0.0.1000.0         DVA0
dvh0.0.0.1000.28
ewa0.0.0.4.29            EWA0            08-00-2B-C4-7F-EE
pga0.0.0.1.2             PGA0            WWN 2000-0000-c921-0c22
pka0.7.0.1.0             PKA0            SCSI Bus ID 7      5.57
pkb0.7.0.1.28           PKB0            SCSI Bus ID 7      5.57
pkc0.7.0.5.29           PKC0            SCSI Bus ID 7      5.57
P00>>>

```

3. Enter <boot> command as shown, using the above CD Drive name :

```

P00>>>boot dqa0
(block dqa0.0.0.15.0)
block 0 of dqa0.0.0.15.0 is a valid boot block
reading 1082 blocks from dqa0.0.0.15.0
bootstrap code read in
base = 5f4000, image_start = 0, image_bytes = 87400
initializing HWRPFB at 2000
initializing page table at 7ffe8000
initializing machine state
setting affinity to the primary CPU
jumping to bootstrap code

```

4. The system will respond by displaying “READ ME FIRST” information on the screen (which you should read and scroll through by pressing the ENTER key), followed by display of the default firmware update utility bootfile name, and the prompt “Bootfile:” At this point, you may press the ENTER key to load the latest (current) update, or you may type a specific bootfile name to load a previous (older) version.

The default bootfile for this platform is

[GS320]GS320_V59B.EXE

Hit <RETURN> at the prompt to use the default bootfile.

Bootfile: <USER HITS ENTER KEY>

```

:
:
<ONE OR TWO PAGES OF PRINTOUT WILL OCCUR HERE>
:
:

```

```

Checking dqa0.0.0.15.0 for the option firmware files. . .
Copying DFXAA320 from dqa0.0.0.15.0. . .
Copying KZPSAA12 from dqa0.0.0.15.0. . .
Copying CIPCA420 from dqa0.0.0.15.0. . .
Copying KG8381A4 from dqa0.0.0.15.0. . .
Copying KG7303A1 from dqa0.0.0.15.0. . .

```

***** Loadable Firmware Update Utility *****

```

-----
Function      Description
-----
Display      Displays the system's configuration table.
Exit         Done exit LFU (reset).

```



List Lists the device, revision, firmware name, and update revision.
Update Replaces current firmware with loadable data image.
Verify Compares loadable and hardware images.
? or Help Scrolls this function table.

UPD>

5. Enter <list> command as shown, to display the various firmware updates available :

UPD> list

Device	Current Revision	Filename	Update Revision
SRM24	V6.9-2	srm_fw	V7.2-1
SRM40	V6.9-2	srm_fw	V7.2-1
SRM	V6.9-2	srm_fw	V7.2-1
pga0	DS3.92A2	kgpsa_8k_fw	DS3.92A2
pgb0	DS3.92A2	kgpsa_8k_fw	DS3.92A2
pgc0	DS3.82A1	kgpsa_8k_fw	DS3.82A1
micro	V6.6(01.22/01:02)	micro_fw	

V6.6(01.22/01:02)

UPD>

6. Enter <update srm*> command as shown, and answer yes to the question (note - if the user enters <update *>, all possible firmware pieces are updated - SRM, Micros, and I/O adapters. Actually, <update *> is the PREFERRED method, so that all firmware is updated at the same time to compatible revisions). The update may take several minutes - DO NOT ABORT THE PROGRAM:

UPD> update srm*

Confirm update on:

SRM28

SRM

[Y/(N)]Y <USER HITS "Y" KEY>

WARNING: updates may take several minutes to complete for each device.

DO NOT ABORT!

SRM28 Updating to v5.9-331... Verifying v5.9-331... PASSED.

SRM Updating to v5.9-331... Verifying v5.9-331... PASSED.

UPD>

7. Enter <exit> command as shown, to leave the LFU and start the new SRM console :

UPD> exit



```
Initializing....
:
<SEVERAL PAGES OF PRINTOUT WILL OCCUR HERE>
:
initializing pka pkb pkc ewa dqa dqb pga

AlphaServer Console V5.9-331, built on Mar 14 2001 at 11:25:22
P00>>>
```

3.2 Checking Firmware version

3.2.1 “show firmware” Command Example (for V7.2firmware)

```
P00>>>show firmware
SRM Console V7.2-1, built on Jun 16 2005
PALcode OpenVMS PALcode V1.98-2,
1
Micro Firmware V6.6
QBB0.PSM PSM V6.6|PSM FS V5.6|XSROM
QBB0.CPU0 SROM V9.0-11
QBB0.CPU1 SROM V9.0-11
QBB0.CPU2 SROM V9.0-11
QBB0.CPU3 SROM V6.0-7
PBP0.SIO SCM V6.6|SCM FS V5.6|SRM
QBB1.PSM PSM V6.6|PSM FS V5.6|XSROM
QBB1.CPU0 SROM V6.0-7
QBB1.CPU1 SROM V6.0-7
QBB1.CPU2 SROM V9.0-11
QBB1.CPU3 SROM V6.0-7
QBB2.PSM PSM V6.6|PSM FS V5.6|XSROM
QBB2.CPU0 SROM V6.0-7
QBB2.CPU1 SROM V9.0-11
QBB2.CPU2 SROM V9.0-11
QBB2.CPU3 SROM V6.0-7
PBP1.SIO SCM V6.6|SCM FS V5.6|SRM
QBB3.PSM PSM V6.6|PSM FS V5.6|XSROM
QBB3.CPU0 SROM V6.0-7
QBB3.CPU1 SROM V6.0-7
QBB3.CPU2 SROM V9.0-11
QBB3.CPU3 SROM V9.0-11
HSW8 HPM V6.6|HPM FS V5.6
PBP0.PBP0 PBM V6.6|PBM FS V5.6
PBP2.PBP0 PBM V6.6|PBM FS V5.6
PBP1.PBP0 PBM V6.6|PBM FS V5.6
PBP3.PBP0 PBM V6.6|PBM FS V5.6
P00>>>
```



3.3 Checking CSB Micro Firmware Revisions

To display the current firmware revisions for the various Micros on the CSB Bus, use the “show csb” command at the SCM Prompt. The following example is for a 16-Processor System, having 3 SCMs, 4 PSMs, 3 PBMs, and 1 HPM Micro. **The firmware revisions shown are not necessarily the latest revisions currently available. They are provided as examples only.**

```
SCM_E0> sho csb

CSB Type           Firmware Revision      FSL Revision  Power State
-----
10  PBM             V06.6 (01.22/01:02)   V5.6 (05.31)  ON
11  PBM             V06.6 (01.22/01:02)   V5.6 (05.31)  ON
12  PBM             V06.6 (01.22/01:02)   V5.6 (05.31)  ON
13  PBM             V06.6 (01.22/01:02)   V5.6 (05.31)  ON
14  PBM             V06.6 (01.22/01:02)   V5.6 (05.31)  ON
15  PBM             V06.6 (01.22/01:02)   V5.6 (05.31)  ON
16  PBM             V06.6 (01.22/01:02)   V5.6 (05.31)  ON
17  PBM             V06.6 (01.22/01:02)   V5.6 (05.31)  ON
18  PBM             V06.6 (01.22/01:02)   V5.6 (05.31)  ON
19  PBM             V06.6 (01.22/01:02)   V5.6 (05.31)  ON
1A  PBM             V06.6 (01.22/01:02)   V5.6 (05.31)  ON
30  PSM             V06.6 (01.22/01:01)   V5.6 (05.31)  ON          SrvSw:
NORMAL
30  XSROM           V06.6 (01.26/00:24)
C0  CPU0/SROM       V9.0-11
C1  CPU1/SROM       V9.0-11
C2  CPU2/SROM       V9.0-11
C3  CPU3/SROM       V9.0-11
C0  IOR0
C1  IOR1
C2  IOR2
C3  IOR3
31  PSM             V06.6 (01.22/01:01)   V5.6 (05.31)  ON          SrvSw:
NORMAL
31  XSROM           V06.6 (01.26/00:24)
C4  CPU0/SROM       V9.0-11
C5  CPU1/SROM       V9.0-11
C6  CPU2/SROM       V9.0-11
C7  CPU3/SROM       V9.0-11
C4  IOR0
C5  IOR1
C6  IOR2
C7  IOR3
32  PSM             V06.6 (01.22/01:01)   V5.6 (05.31)  ON          SrvSw:
NORMAL
32  XSROM           V06.6 (01.26/00:24)
C8  CPU0/SROM       V9.0-11
C9  CPU1/SROM       V9.0-11
CA  CPU2/SROM       V9.0-11
CB  CPU3/SROM       V9.0-11
C8  IOR0
C9  IOR1
```



Firmware Update Procedures

33	PSM	V06.6	(01.22/01:01)	V5.6 (05.31)	ON	SrvSw:
NORMAL						
33	XSROM	V06.6	(01.26/00:24)			
CC	CPU0/SROM	V9.0-11			ON	
CD	CPU1/SROM	V9.0-11			ON	
CE	CPU2/SROM	V9.0-11			ON	
CC	IOR0				ON	
CD	IOR1				ON	
34	PSM	V06.6	(01.22/01:01)	V5.6 (05.31)	ON	SrvSw:
NORMAL						
34	XSROM	V06.6	(01.26/00:24)			
D0	CPU0/SROM	V9.0-11			ON	
D1	CPU1/SROM	V9.0-11			ON	
D2	CPU2/SROM	V9.0-11			ON	
D3	CPU3/SROM	V9.0-11			ON	
D0	IOR0				ON	
D1	IOR1				ON	
35	PSM	V06.6	(01.22/01:01)	V5.6 (05.31)	ON	SrvSw:
NORMAL						
35	XSROM	V06.6	(01.26/00:24)			
D4	CPU0/SROM	V6.0-7			ON	
D5	CPU1/SROM	V6.0-7			ON	
D6	CPU2/SROM	V6.0-7			ON	
D7	CPU3/SROM	V6.0-7			ON	
D4	IOR0				ON	
D5	IOR1				ON	
D6	IOR2				ON	
D7	IOR3				ON	
36	PSM	V06.6	(01.22/01:01)	V5.6 (05.31)	VAUX	SrvSw:
SERVICE						
36	XSROM	V06.6	(01.26/00:24)			
D8	CPU0/SROM	X0.0-0			OFF	
D9	CPU1/SROM	X0.0-0			OFF	
DA	CPU2/SROM	X0.0-0			OFF	
DB	CPU3/SROM	X0.0-0			OFF	
D8	IOR0				OFF	
D9	IOR1				OFF	
DA	IOR2				OFF	
DB	IOR3				OFF	
37	PSM	V06.6	(01.22/01:01)	V5.6 (05.31)	ON	SrvSw:
NORMAL						
37	XSROM	V06.6	(01.26/00:24)			
DC	CPU0/SROM	V6.0-7			ON	
DD	CPU1/SROM	X0.0-7			ON	
DE	CPU2/SROM	V6.0-7			ON	
DC	IOR0				ON	
DD	IOR1				ON	
DE	IOR2				ON	
DF	IOR3				ON	
40	HPM	V06.6	(01.22/01:02)	V5.6 (05.31)	ON	
E0	SCM MASTER	V06.6	(01.22/01:02)	V5.6 (05.31)	ON	
E1	SCM SLAVE	V06.6	(01.22/01:02)	V5.6 (09.13)	ON	
Ineligible						
E2	SCM SLAVE	V06.6	(01.22/01:02)	V5.6 (09.13)		

SCM_E0>



3.4 Updating CSB Micro Firmware Using the CD

NOTE 1 : It is recommended that you run the LFU from the serial line with the “console” environment variable set to “serial” mode. In “graphics” mode, after updating CSB Micros, the graphics monitor will go blank, and you will have to do an SCM “p on” command from the serial line, to restart the system.

NOTE 2 : Sometimes new revisions of firmware may require the EEPROM (which contains CSB NVR settings) to be re-initialized and customized settings to be lost. It is recommended that before the LFU is run, the User should check for customized settings using SCM “show nvr” command, and write them down for later restoration using the SCM “set” command. After the LFU is run the user should do “show nvr” and if the message is printed “~E~ EEPROM VERSION MISMATCH. Execute Build EEPROM Cmd”, the user should do a “build eeprom” command, followed by “set” commands to restore any customized settings.

NOTE 3 : Before using the LFU to update CSB Micro Firmware on Partitioned systems, the user **MUST DE-PARTITION THE SYSTEM**. It is recommended that the user first do a “show nvr” and write down the value of the NVR variable “hp_count”, and then “set hp_count 0” to disable partitioning, followed by commands to “p off” and “p on”.

```
SCM_E0> set hp_count 0
SCM_E0> p off
.
.
.
SCM_E0> p on
```

Then the user should run the LFU, and after that the user should use the “set hp_count x” (where x is the saved value of hp_count) command to restore partitioning.

CSB Micro Firmware Update Example Using LFU :

1. Load the “Alpha Systems Firmware Update CD Vx.x” into the CD-ROM Drive. Then, from the SRM Console prompt, Initialize the System :

```
P00>>>init

OpenVMS PALcode V1.98-2, Tru64 UNIX PALcode V1.92-1

system = QBB 0 1 2 3          + HS
  QBB 0 = CPU 0 1 2 3 + Mem 0 2 3 + Dir + IOP + PCA 0 1      + GP (Hard QBB 0)
  QBB 1 = CPU 0 1 2 3 + Mem 0          + Dir + IOP + PCA          + GP (Hard QBB 1)
  QBB 2 = CPU 0 1 2 3 + Mem 0 1          + Dir + IOP + PCA          + GP (Hard QBB 2)
  QBB 3 = CPU 0 1 2 3 + Mem 0 1          + Dir + IOP + PCA          2 + GP (Hard QBB 3)
micro firmware version is V6.6
shared RAM version is 1.6
.
.
<SEVERAL PAGES OF PRINTOUT WILL OCCUR HERE>
.
.
```



AlphaServer Console V7.2-7, built on Jun 1 2006 at 13:40:02
P00>>>

2. Enter <show dev> to find name of CD-ROM Drive (dqa0 in this example) :

```
P00>>>sho dev
dka0.0.0.1.0          DKA0          COMPAQ BB00921B91  3B05
dkb0.0.0.1.28        DKB0          COMPAQ BB00921B91  3B05
dkc0.0.0.5.29        DKC0          COMPAQ BB00911CA0  3B05
dkc100.1.0.5.29      DKC100        COMPAQ BB00911CA0  3B05
dkc200.2.0.5.29      DKC200        COMPAQ BB00911CA0  3B05
dkc300.3.0.5.29      DKC300        COMPAQ BB00911CA0  3B05
dkc400.4.0.5.29      DKC400        COMPAQ BB00911CA0  3B05
dkc500.5.0.5.29      DKC500        COMPAQ BB00911CA0  3B05
dqa0.0.0.15.0        DQA0          COMPAQ CDR-8435    0013
dqb0.0.0.15.28       DQB0          COMPAQ CDR-8435    0013
dva0.0.0.1000.0      DVA0
dvh0.0.0.1000.28
dva0.0.0.4.29        EWA0          08-00-2B-C4-7F-EE
pga0.0.0.1.2         PGA0          WWN 2000-0000-c921-0c22
pka0.7.0.1.0         PKA0          SCSI Bus ID 7      5.57
pkb0.7.0.1.28        PKB0          SCSI Bus ID 7      5.57
pkc0.7.0.5.29        PKC0          SCSI Bus ID 7      5.57
P00>>>
```

3. Enter <boot> command as shown, using the above CD Drive name :

```
P00>>>boot dqa0
(block dqa0.0.0.15.0)
block 0 of dqa0.0.0.15.0 is a valid boot block
reading 1082 blocks from dqa0.0.0.15.0
bootstrap code read in
base = 5f4000, image_start = 0, image_bytes = 87400
initializing HWRPB at 2000
initializing page table at 7ffe8000
initializing machine state
setting affinity to the primary CPU
jumping to bootstrap code
```

4. The system will respond by displaying “READ ME FIRST” information on the screen (which you should read and scroll through by pressing the ENTER key), followed by display of the default firmware update utility bootfile name, and the prompt “Bootfile:” At this point, you may press the ENTER key to load the latest (current) update, or you may type a specific bootfile name to load a previous (older) version.

```
The default bootfile for this platform is
[GS320]GS320_V59B.EXE
Hit <RETURN> at the prompt to use the default bootfile.
Bootfile: <USER HITS ENTER KEY>
.
.
<ONE OR TWO PAGES OF PRINTOUT WILL OCCUR HERE>
.
.
Checking dqa0.0.0.15.0 for the option firmware files. . .
Copying DFXAA320 from dqa0.0.0.15.0. . .
Copying KZPSAA12 from dqa0.0.0.15.0. . .
Copying CIPCA420 from dqa0.0.0.15.0. . .
```



```
Copying KG8381A4 from dqa0.0.0.15.0. . .  
Copying KG7303A1 from dqa0.0.0.15.0. . .
```

***** Loadable Firmware Update Utility *****

Function	Description
Display	Displays the system's configuration table.
Exit	Done exit LFU (reset).
List	Lists the device, revision, firmware name, and update revision.
Update	Replaces current firmware with loadable data image.
Verify	Compares loadable and hardware images.
? or Help	Scrolls this function table.

UPD>

5. Enter <list> command as shown, to display the various firmware updates available :

UPD> list

Device	Current Revision	Filename	Update Revision
SRM28	v5.9-331	srm_fw	v5.9-331
SRM	v5.9-331	srm_fw	v5.9-331
pga0	DS3.03A1	kgpsa_8k_fw	DS3.81A4
micro	V5.8(11.08/01:01)	micro_fw	V5.9(03.14/11:04)
		cipca_fw	A420
		dfxaa_fw	3.20
		kgpsa_7k_fw	SS3.03A1
		kzpsa_fw	A12

UPD>

6. Enter <update micro> command as shown, and answer yes to the question (note - if the user enters <update *>, all possible firmware pieces are updated - SRM, Micros, and I/O adapters. Actually, <update *> is the PREFERRED method, so that all firmware is updated at the same time to compatible revisions). The update may take several minutes - DO NOT ABORT THE PROGRAM :

UPD> update micro

Confirm update on:

micro

[Y/(N)]Y <USER HITS "Y" KEY>

WARNING: updates may take several minutes to complete for each device.

DO NOT ABORT!

micro Updating to V5.9(03.14/11:04)...



```
Updating SCM nodes E0,E1
Update Cmd processed
Transferring hex file.....Flash ON.....Flash ON.....Flash
ON.....Flash ON.....
:
:
<SEVERAL PAGES OF PRINTOUT WILL OCCUR HERE>
:
:
~I~ SCM powered via PBM
SCM_E0>
Firmware Update is now complete. If you require a partitioned system,
please set your HP_COUNT and 'POWER ON -ALL'. For non-partitioned systems
enter 'POWER ON'

SCM_E0>
~I~ CSB Node 40 connection added
SCM_E0>
```

7. Enter <p on> command as shown :

```
SCM_E0> p on
Powering on PCI Box 0
Powering on PCI Box 1
QBB-0 Powering ON

~I~ Testing OCP Switch- passed
Power ON Phase INIT
QBB-1 Powering ON
QBB-2 Powering ON
QBB-3 Powering ON
:
:
<SEVERAL PAGES OF PRINTOUT WILL OCCUR HERE>
:
:
AlphaServer Console V5.9-331, built on Mar 14 2001 at 11:25:22
P00>>>
```

3.5 Updating PCI I/O Adapter Firmware Using the CD

NOTE: It is recommended that you run the LFU from the serial line with the “console” environment variable set to “serial” mode. In “graphics” mode, after updating CSB Micros, the graphics monitor will go blank, and you will have to do an SCM “p on” command from the serial line, to restart the system.

PCI I/O Adapter Firmware Update Example Using LFU :

- 1. Load the “Alpha Systems Firmware Update CD Vx.x” into the CD-ROM Drive. Then, from the SRM Console prompt, Initialize the System :**



```
P00>>>init

OpenVMS PALcode V1.90-3, Tru64 UNIX PALcode V1.86-2

system = QBB 0 1 2 3          + HS
  QBB 0 = CPU 0 1 2 3 + Mem 0 2 3 + Dir + IOP + PCA 0 1      + GP (Hard QBB 0)
  QBB 1 = CPU 0 1 2 3 + Mem 0          + Dir + IOP + PCA          + GP (Hard QBB 1)
  QBB 2 = CPU 0 1 2 3 + Mem 0 1      + Dir + IOP + PCA          + GP (Hard QBB 2)
  QBB 3 = CPU 0 1 2 3 + Mem 0 1      + Dir + IOP + PCA          2 + GP (Hard QBB 3)
micro firmware version is V5.9
shared RAM version is 1.4
.
.
<SEVERAL PAGES OF PRINTOUT WILL OCCUR HERE>
.
.
AlphaServer Console V5.9-331, built on Mar 14 2001 at 11:25:22
P00>>>
```

2. Enter <show dev> to find name of CD-ROM Drive (dqa0 in this example) :

```
P00>>>sho dev
dka0.0.0.1.0          DKA0          COMPAQ BB00921B91 3B05
dkb0.0.0.1.28        DKB0          COMPAQ BB00921B91 3B05
dkc0.0.0.5.29        DKC0          COMPAQ BB00911CA0 3B05
dkc100.1.0.5.29      DKC100       COMPAQ BB00911CA0 3B05
dkc200.2.0.5.29      DKC200       COMPAQ BB00911CA0 3B05
dkc300.3.0.5.29      DKC300       COMPAQ BB00911CA0 3B05
dkc400.4.0.5.29      DKC400       COMPAQ BB00911CA0 3B05
dkc500.5.0.5.29      DKC500       COMPAQ BB00911CA0 3B05
dqa0.0.0.15.0        DQA0          COMPAQ CDR-8435 0013
dqb0.0.0.15.28       DQB0          COMPAQ CDR-8435 0013
dva0.0.0.1000.0      DVA0
dvh0.0.0.1000.28
ewa0.0.0.4.29        EWA0          08-00-2B-C4-7F-EE
pga0.0.0.1.2         PGA0          WWN 2000-0000-c921-0c22
pka0.7.0.1.0         PKA0          SCSI Bus ID 7 5.57
pkb0.7.0.1.28        PKB0          SCSI Bus ID 7 5.57
pkc0.7.0.5.29        PKC0          SCSI Bus ID 7 5.57
P00>>>
```

3. Enter <boot> command as shown, using the above CD Drive name :

```
P00>>>boot dqa0
(block dqa0.0.0.15.0)
block 0 of dqa0.0.0.15.0 is a valid boot block
reading 1082 blocks from dqa0.0.0.15.0
bootstrap code read in
base = 5f4000, image_start = 0, image_bytes = 87400
initializing HWRPB at 2000
initializing page table at 7ffe8000
initializing machine state
setting affinity to the primary CPU
jumping to bootstrap code
```

4. The system will respond by displaying “READ ME FIRST” information on the screen (which you should read and scroll through by pressing the ENTER key), followed by display of the default firmware update utility bootfile name, and the prompt “Bootfile:” At this point, you may press the ENTER key to load the latest (current) update, or you may type a specific bootfile name to load a previous (older) version.



The default bootfile for this platform is

[GS320]GS320_V59B.EXE

Hit <RETURN> at the prompt to use the default bootfile.

Bootfile: <USER HITS ENTER KEY>

.
.
<ONE OR TWO PAGES OF PRINTOUT WILL OCCUR HERE>

Checking dqa0.0.0.15.0 for the option firmware files. . .
Copying DFXAA320 from dqa0.0.0.15.0. . .
Copying KZPSAA12 from dqa0.0.0.15.0. . .
Copying CIPCA420 from dqa0.0.0.15.0. . .
Copying KG8381A4 from dqa0.0.0.15.0. . .
Copying KG7303A1 from dqa0.0.0.15.0. . .

***** Loadable Firmware Update Utility *****

Table with 2 columns: Function, Description. Rows include Display, Exit, List, Update, Verify, and ? or Help.

UPD>

5. Enter <list> command as shown, to display the various firmware updates available :

UPD> list

Table with 4 columns: Device, Current Revision, Filename, Update Revision. Lists various hardware components and their firmware versions.

UPD>

6. In this example, we will update the KGPSA Adapter (pga0). Enter <update pga*> command as shown, and answer yes to the question (note - if the user enters <update *>, all possible firmware pieces are updated - SRM, Micros, and I/O adapters. Actually,



<update *> is the PREFERRED method, so that all firmware is updated at the same time to compatible revisions). The update may take several minutes - DO NOT ABORT THE PROGRAM :

```
UPD> update pga*

Confirm update on:
pga0
[Y/(N)]Y <USER HITS "Y" KEY>
WARNING: updates may take several minutes to complete for each device.

                DO NOT ABORT!

pga0           Updating to DS3.81A4...  Verifying DS3.81A4...  PASSED.

UPD> exit
```

7. Enter <exit> command as shown, to leave the LFU and restart the SRM console :

```
UPD> exit

Initializing...
.
.
<SEVERAL PAGES OF PRINTOUT WILL OCCUR HERE>
.
.
initializing pka pkb pkc ewa dqa dqb pga

AlphaServer Console V5.9-331, built on Mar 14 2001 at 11:25:22
P00>>>
```

3.6 Procedure for Recovering from a Failed LFU Update


In the case of an LFU update failing the following information will describe the steps necessary to recover a CSB node to the point at which the LFU may be tried a second time.

When a CSB node fails to update it will most likely result in that node being in its Failsafe Loader (FSL). Once in this state the node can no longer be updated via the LFU utility and must be updated serially, following the steps below.

3.6.1 Hardware Connections

Use of the SCM update command requires a physical connection to the master SCM (unless the failed node is a slave SCM, in which case connect to that slave's local terminal port). If the system management console is used, you need not connect a laptop but can execute update procedures from there.

Figure: Connecting a Laptop to the Local Terminal Port



PK1273

The above figure shows the connection made between a laptop and the local terminal port on the standard I/O module in the master PCI box. On this module resides the CSB master SCM. Use two nine pin to MMJ connectors (H8571-J), one for the COM1 port and the other for the laptop, and connect the two using a DEC connect office cable.

NOTE : If you are using the system management console (SMC) to do firmware updates, you need not connect your laptop since the SMC is already connected to the master PCI box.

3.6.2 PC/Laptop Operating System Preparation

When the SCM update command is used, firmware update files are downloaded from a PC or laptop into the master SCM module. Certain COM1 port settings are required.

Example: COM1 Port Settings for Windows NT 4.0

1. From Start go to Settings and select Control Panel.
2. From Control Panel select Ports.
3. From Ports select COM1 and Settings.
4. At Settings for COM1, set:

Baud rate:	9600
Data Bits:	8
Parity:	None



Stop Bits: 1
Flow Control: Xon/Xoff
then select Advanced

5. At Advanced Setting for COM1, disable (uncheck) FIFO Enable and leave all other settings at the default.
6. Click OK back through the dialog boxes, shutdown, reboot and verify that these settings stuck.



Example: COM1 Port Settings for Windows 2000

1. From Start go to Settings and select Control Panel.
2. From Control Panel select System.
3. From System select the Hardware tab.
4. From the Hardware tab select Device Manager.
5. Expand Ports and select Communications Port (COM1).
6. At the Communications Port (COM1) Properties, set:
Bits per second: 57600
Data Bits: 8
Parity: None
Stop Bits: 1
Flow Control: Xon/Xoff
then select Advanced.
7. At the Advanced Settings for COM1, deselect Use FIFO buffers.
8. Click OK back through the dialog boxes. There is no need to reboot.

Example: COM1 Port Settings for Windows 95

1. From Start go to Settings and select Control Panel.
2. From Control Panel select System.
3. From System Properties select the Hardware Manager tab.
4. Expand Ports and select Communications Port (COM1).
5. At the Communications Port (COM1) Properties, select the Port Settings tab and set:
Bits per second: 57600
Data Bits: 8
Parity: None
Stop Bits: 1
Flow Control: Xon/Xoff
then select Advanced.
6. At the Advanced Port Settings, deselect Use FIFO buffers.
7. Click OK back through the dialog boxes. There is no need to reboot.

3.6.3 Terminal Emulator Settings



When the SCM update command is used, firmware update files are downloaded from a host PC COM1 port to the master SCM local port on the standard I/O module. Certain terminal emulator settings are required.

Example: KEAterm V5.1 Session for PC or Laptop COM1 Port

1. From Start go to Programs and select KEA!VT and then KEA!
2. At the Session Template select Serial – click Next>.
3. At Connection Type select Serial – click Next>.
4. At Connection select the General tab and set
Port name: COM1
Speed: 9600
– click Next>.
5. Then select the Options tab and in the Flow Control section set:
Data to host: Xon/Xoff
Data from host: Xon/Xoff
6. Then select the Rate Limiting tab and deselect (uncheck) both
Limit data rate during Paste and ASCII send and
Limit data rate during keyboard input and reporting
– click Next>.
7. At Terminal Type select VT400-8bit – click Next>.
8. At File Transfer Protocol select ASCII – click Next>.
9. Click Finish to open a KEA terminal session.
10. From the Options menu select History.
Select the VT Advanced tab
Select (check) Auto wrap lines
Click OK.
11. From the File menu select Save Session as
Set Name as something like WF_SCM
Click Save.

Example: PowerTerm 525 Settings

1. From Start go to Programs and select PowerTerm.
2. At Connect set:
Session type COM
Terminal type VT420-8
Baud Rate 9600



```

c3 CPU3/SROM T4.2-7 OFF
c0 IOR0 OFF
c1 IOR1 OFF
c2 IOR2 OFF
c3 IOR3 OFF
31 PSM T04.6 (11.03/01:07) T4.2 (09.08) ON SrvSw: NORMAL
31 XSROM T04.6 (11.03/02:19)
c4 CPU0/SROM T4.2-7 On
c5 CPU1/SROM T4.2-7 On
c6 CPU2/SROM T4.2-7 On
c7 CPU3/SROM T4.2-7 On
c4 IOR0 On
c5 IOR1 On
40 HPM T04.6 (11.03/01:11) T4.2 (09.08) ON
e0 SCM MASTER T04.6 (11.03/01:13) T4.2 (09.08) ON
e1 SCM SLAVE T04.6 (11.03/01:13) T4.2 (09.08) ON Ineligible
e2 SCM SLAVE T04.6 (11.03/01:13) T4.2 (09.08) ON Ineligible
e6 SCM SLAVE T04.6 (11.03/01:13) T4.2 (09.08) ON Ineligible
SCM_E0> update -csb 30 4
Initiate HEX file transfer from host (press ESC-ESC to abort):

```

Conditions to Note When Using This Update Method

A master and slave SCM may be updated using this method but a master SCM cannot update a slave. To update either a master or slave the device downloading the SCMR0M.HEX file must be connected physically to the target standard I/O local port.

When updating the XSROM code, the entire system may be up and running operating systems.

A consequence of updates to any of the microprocessors (with the exception of the XSROM on the PSM) is that they immediately reset once the new firmware downloads. Therefore, you want to minimize the effect of the reset on the rest of the system by isolating the QBB/partition.

When updating a PSM, the partition in which the PSM resides should be powered off.

When updating a PBM, the PCI I/O subsystem in which the PBM resides must be removed from the resources available to an operating system.

When updating an HPM, the system should be powered off.

The above Example shows a sample master SCM update of a PSM module in QBB0 :

1. The target device to be updated must be powered off. In this example the PSM is assumed to be in partition 0. It is also assumed that partition 0 has been appropriately powered off using the SRM **power off** command prior to the SCM **power off -par 0** command.
2. The **show csb** command shows the target off and the PSM switch in the Service position.

Example : Using the Update Command (Continued)

```

SCM_E0> update -csb 30 1
Initiate HEX file transfer from host (press ESC-ESC to abort):

Initiate transfer of the file PSMROM.HEX to the COM1 port 2

```

For KEAterm



From the Tools menu goto File Transfer and select Send to Host
Change the Files of type: to All Files (*.*)
Browse for and select the file PSMROM.HEX.
Click on OK.

For PowerTerm 525

From the Communication menu select Send File...
At Send File select the Ascii tab
Browse for and select the file PSMROM.HEX by clicking on the browse button
next to the File Name input box.
Click OK.

```
:02000002C0003C  
Transferring hex file . . . . .  
~I~ Flashing node 30 (please wait)  
CSB download of .HEX file complete
```

```
Flash Update complete.  
CSB Node 30 connection lost  
CSB Node 30 connection added  
SCM_E0>
```

3

Note in the above continuation of the example :

1. The SCM **update** command is issued. Note that it is possible to update several PSMs at a time with the command: **update -csb 30,31,32...**
2. Be sure that the terminal emulator is configured properly for the file transfer. (See previous subsection). The PSMROM.HEX file is transferred to the COM1 port.
3. The flash update completes.