## INSERTING A TK50 TAPE CARTRIDGE

Use the following procedure to insert a TK50 cartridge. First-time users should refer to the TK50 Tape Drive Subsystem User's Guide (EK-OTK50-UG) and the TK50 Tape Drive Subsystem User Reference Card (EK-OTK50-RC) for instructions.

1. Make sure the Load/Unload button is out.

2. Set the TK50 subsystem power switch to 1 (on), then set the computer power switch to 1 (on).

    a. The red light stays on during the tape drive power-up self-test (about 5 to 15 seconds).

    b. The red light goes off and the green light goes on.

3. Lift the cartridge insert/release handle (Figure 4-5).

SHR-0302-84-B

Figure 4-5   Lifting Cartridge Insert/Release Handle