

4. Inspect the take-up leader inside the TK50.

Make sure that the take-up leader inside the tape drive is in the correct position, as shown below. Since the take-up leader in the TK50 must mate with the leader inside the tape cartridge, it is important that both are in their correct positions.

CAUTION: Do not try to fix the take-up leader inside the tape drive. If it is not in the correct position, call Digital Field Service.

